

Inspection Photos

05/20/2026

Operator: Wesco Operating Inc #95520

Location ID: 312877

Inspection Doc: 719201175

Moffat County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



Photo 1: Photos showing an overview of the location looking north and south, respectively. Ongoing soil sampling efforts are occurring at the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



Photo 2: Photos showing an overview of the location looking east and west, respectively. Ongoing soil sampling efforts are occurring at the location.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



Photo 3: Photos showing orange plastic fencing around a portion of the open excavation is in disrepair and requires maintenance.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



Photo 4: Photos showing stained soils at the southern portion of the location near utility equipment. Cleaning/removal of stained soils is required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



Photo 5: Photos showing examples of unused equipment/supplies that is scattered throughout the location and requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



Photo 6: Photos showing an example of a soil stockpile; multiple stockpiles are present at the location. Stormwater BMP's are missing or insufficient; comply with Rule 1002.f.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



Photo 7: Photos showing examples of rilling and erosion that is occurring on the western edge of the pad; stormwater BMP's appear missing or insufficient. Stormwater BMP's are required until the location achieves final reclamation pursuant to 1004 series Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



Photo 8: Photo showing an overview of the access road leading to the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



Photo 9: Photo showing hoary cress and cheatgrass is present in tertiary amounts around the edges of the pad.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



Photo 10: Photos showing an overview of the western/southern interim area and the eastern cut slopes at the location. Vegetation is well established and no issues were observed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources