

# Inspection Photos

05/20/2026

Operator: Wesco Operating Inc #95520

Location ID: 312864

Inspection Doc: 719201180

Moffat County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



**Photo 1:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



**Photo 2:** Stained soils appear to be present on the northwestern portion of the location near utility equipment; cleaning/removal of stained soils is required.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



**Photo 3:** Orange plastic fencing around open excavations is down/in disrepair. Maintenance is required to prevent access.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



**Photo 4:** Photos showing erosion and rilling is occurring on the northern edge of the pad; implementation or maintenance of stormwater BMP's is required until the location receives a passing final reclamation inspection.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



**Photo 5:** Photos showing trash/debris that is scattered throughout the location and requires removal.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



**Photo 6:** Photos showing trash/debris that is scattered throughout the location and requires removal.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



**Photo 7:** Soil stockpiles at the location appear to be missing stormwater BMP's; implementation and/or maintenance of stormwater BMP's on soil stockpiles is required.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



**Photo 8:** Photos showing the nearby reference area, directly west of the location. The reference area is primarily composed of big sagebrush, with secondary amounts of scrub oak.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Wesco Operating Inc #95520

Location ID: 312877



**Photo 9:** Photos showing surface equipment such as utility line and above-ground flowlines that require removal before the location receives a passing final reclamation inspection.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources