

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/20/2026

Submitted Date:

05/26/2026

Document Number:

719201180

FIELD INSPECTION FORM

Loc ID: 312864 Inspector Name: Gaasche, Emily On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

4 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 95520

Name of Operator: WESCO OPERATING INC

Address: 120 S DURBIN STREET

City: CASPER State: WY Zip: 82602

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Meidinger, Brian		brianm@kirkwoodcompanies.com	
Weinert, Dave	(307) 577-5329	davew@kirkwoodcompanies.com	
Knigge, Josh	(307) 259-7834	joshk@kirkwoodcompanies.com	
Coit, Parker		parker.coit@wsp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222662	WELL	PA	06/24/2025	OW	081-06022	MAUDLIN GULCH 15	RI
312864	LOCATION	CL			-	MAUDLIN GULCH UNIT-64N95W 35NWNE	RI

General Comment:

On 05/20/2026, NW Reclamation Specialist Emily Gaasche conducted a reclamation inspection at Wesco Operating Inc's MAUDLIN GULCH UNIT-64N95W/35NWNE (Maudlin Gulch #15) location in Moffat County, Colorado.

The following compliance issues were observed during this inspection:

- Stained soils
- Trash/debris
- Soil stockpiles lacking stormwater BMP's
- Stormwater

Refer to the Location, Reclamation and Stormwater sections of this report for additional details.

Refer to the photo-documentation attached to this report for additional details.

Any outstanding CA's from previous inspections remain applicable.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

TRASH

Comment: [Trash and debris is scattered throughout the location; removal is required. See photo attachment for more details.](#)

Corrective Action: [Comply with Rule 606.d.](#)

Date: 06/09/2026

Overall Good:

Spills:

Type

Area

Volume

Other

Comment: [Stained soils are present on the northwestern portion of the location. Clean up and removal is required; see photo attachment for more details.](#)

Corrective Action: [Comply with Rule 912.a. and clean up/remove stained soils.](#)

Date: 06/27/2026

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: [Orange plastic fencing around both of the open excavations are in disrepair. Fencing around the wells are not adequate to prevent livestock or wildlife access.](#)

Corrective Action: [Install or repair BMP's to prevent access into the excavated area](#)

Date: 06/09/2026

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 222662 Type: WELL API Number: 081-06022 Status: PA Insp. Status: RI

Facility ID: 312864 Type: LOCATION API Number: - Status: CL Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Pursuant to Form 6(s) #404277116, the well was plugged and abandoned on 6/24/2025. An open remediation project is occurring, open excavations are present and the plugged well has not yet been backfilled. Surface equipment, such as utility lines and above ground flowlines, remain at the location. Trace amounts of cheatgrass and hoary cress, both noxious weeds, are present along the margins of the pad. Weed management is not required at this time, however, ongoing weed monitoring and maintenance is required until the location receives a passing final reclamation inspection.

Corrective Action:

Date _____

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Erosion and rilling is occurring on the northern edge of the pad; stormwater BMP's appear to be missing or insufficient; implementation or maintenance of stormwater BMP's is required.

Soil stockpiles related to open excavations are present at the location. Stormwater BMP's appear to be missing or insufficient. Implementation or maintenance of stormwater BMP's to protect the soil stockpile from erosion and degradation is required.

Corrective Action:

Comply with Rule 1002.f.

Date: _____

Pits:

NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
	gaaschee	05/26/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719201181	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7558684