

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/20/2026

Submitted Date:

05/21/2026

Document Number:

700300893

FIELD INSPECTION FORM

Loc ID 325560 Inspector Name: LABOWSKIE, STEVE On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
8 Number of Comments
6 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 53255
 Name of Operator: MARALEX RESOURCES INC
 Address: P O BOX 338
 City: IGNACIO State: CO Zip: 81137

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, O'hare		mollieo@maralexinc.com	San Juan inspections
Bechtolt, Phoebe		pbechtolt@maralexinc.com	

General Comment:

On may 12, 13 and 20 ECMC SW Compliance Supervisor documented upset condition at heated horizontal with pressure relief activated continuously. This is also a follow-up inspection to previous 4.29.26 inspection doc# 719001938

Documentation was through phine camera with audio and FLIR IR camera which shows gas venting to atmosphere. (see attachment section for Inks to uploaded color/audio and FLIR videos.

Vegetation was observed growing up around fire tube of heated separator and within 25' of separator which caused a new corrective action per rule 610.k. Previous corrective action from doc# 719001938 has not been performed

An open top tank which appears to not have fluids but does have material at bottom. Tanks berm capacity and permeability are inadequate and NFPA placard incorrectly has a "0" for flamabilty.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank has NFPA placard with 0 for flammability. CBM water is considered to have netrained gas even post separation and must have at least a 1 flamability ratingj on NFPA placard (see NFPA 704)		
Corrective Action:	Correct NFPA placard per Rule 605.h(1)e	Date:	06/19/2026

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Good Housekeeping:			
Type	WEEDS		
Comment:	Previous corrective action from FIR doc# 719001938 has not been performed		
Corrective Action:	Control weeds and undesireable vegetation per rule 606	Date:	05/07/2026
Type	OTHER		
Comment:	Tall vegetation near fire tube of heated separator is a fire hazard.		
Corrective Action:	Keep areas 25 feet from wellheads, tanks and separators clear of material that might constitute a fire hazard per Rule 610.k	Date:	05/25/2026

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No
 Comment:
 Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	Open Top		37.122411,-107.592728	
Comment:						
Corrective Action:						Date:

Paint	
Condition	
Other (Content)	
Other (Capacity)	80 bbl
Other (Type)	open top fiberglass

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	No water reported for well since 2014. Tank not signed or operated as an out of service vessel. Berms lack capacity for labeled volume and have visible areas of cracked and separated soil. Tank should only be put into "out of service" state if plans are to return to service. Otherwise tank would be considered not necessary for oil and gas operations.			
Corrective Action:	Instroll or maintain adequate secondary containment			Date: 06/19/2026

Venting:			
Yes/No	YES		
Comment:	Gas venting from separator pressure revlief valve on 5/12, 5/13 and 5/20		
Corrective Action:	Cease venting through separation equipment		Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

