

FORM INSP <small>Rev X/20</small>	State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>05/21/2026</u> Submitted Date: <u>05/21/2026</u> Document Number: <u>719002050</u>
FIELD INSPECTION FORM			

Loc ID 333661 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

4 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
,		mollieo@maralexinc.com	All Inspections
,		pbechtolt@maralexinc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271095	WELL	PR	11/01/2025	GW	067-08915	KEEGAN PATRICK 33-7-11 #1	PR
294235	WELL	PR	09/01/2025	GW	067-09478	KEEGAN PATRICK 33-7-11 3B	PR

General Comment:

[Inspection Report Summary](#)
 On 5/20/26 | Inspector Charles Garcia conducted an on-site follow up inspection. LANDOWENER COMPLAINT Location:KEEGAN PATRICK 33-7-11 #1,KEEGAN PATRICK 33-7-11 #3 Operator:MARALEX RESOURCES INC
 API#: 067-08915
 API# 067-09478
 County: LaPlata
 All prior CA's still stand
 FIR DOC #719001934
 FIRR DOC #404648930
 1 OF 5 CA'S RESOLVED

Location			
Lease Road:			
Type	Access		
comment:	Culvert at entrance of location DAMAGED STORM WATER AND IRRIGATION WATER causing extensive damage to access road. See location, pictures. Corrective ActionL Stormwater management Erosion Control Install or repair required BMPs per Rule 1002.f.(2)C		
Corrective ActionL	Corrective ActionL Stormwater management Erosion Control Install or repair required BMPs per Rule 1002.f.(2)C CA HAS NOT BEEN RESOLVED CA DATE 5/20/26	Date:	
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:			
Corrective Action:			
Date: _____			
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Pump Jack			#
Comment:	CORRECTIVE ACTION RESOLVED Both belt guards for pump jacks have been removed and are on the side of skid SEELLOCATION PICTURES. Removing belt guards and safety equipment does not meet manufacturers specifications for safe working conditions. For protection of the public, livestock and wildlife. Corrective Action: IMMEDIATE ACTION REQUIRED. Equipment must be returned to manufacturers safety specifications FOR SAFETY AND PROTECTION OF THE PUBLIC, LIVESTOCKAND WILDLIFE FOR ONGOING OPERATIONS BELT GUARDS HAVE BEENINSTALLED SEE LOCATION PICTURES		
Corrective Action:			Date:
Type: Deadman # & Marked			#
Comment:	DEADMAN OFF LOCATION ON NORTH SIDE UNMARKED SEE LOCATION PICTURES		
Corrective Action:			Date:
Type: Pump Jack			#
Comment:	Corrective Action NOT RESOLVED IMMEDIATE ACTION REQUIRED Comply with the fencing requirements per the 1002 Rules FOR PROTECTION OF THE PUBLIC, LIVESTOCK AND WILDLIFE. Hog wire fencing has been IMPROVED to a thicker gauge wire however Not stable see location, pictures. For the #1 and #3B the panels are sufficient height and gauge but insufficiently secured to t-posts by mechanics blue. Fencing must be constructed and well maintained as defined in accepted specifications such as NRCS Code 382 and Colorado Dept. of Agriculture guidelines. At that at time of inspection the units were not running and there was no direct safety issue for livestock unless they resume operation.		
Corrective Action:	Adequately install livestock barricade panels		Date:
Type: Other			#
Comment:	WELLHEAD HAS LUBRICATION SYSTEM LEAK IMPACTING SOIL SEE LOCATION PICTURES CA NOT RESOLVED ORIGINAL CA DATE5/3/26		

Corrective Action:	Corrective Action: 608.e MAINTAIN LUBRICATION SYSTEM CLEAN UP IMPACTED SOIL AROUND WELLHEAD rule 1002.f	Date:	
--------------------	---	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 271095 Type: WELL API Number: 067-08915 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 294235 Type: WELL API Number: 067-09478 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 15 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts	Fail					

Comment: **No culvert at entrance of location IRRIGATION WATER AND STORM WATER causing extensive damage to access road. See location, pictures. CA NOT RESOLVED SEE LOCATION PICTURES ORIGINAL CA DATE 5/3/26**

Corrective Action: **Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C**

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
1 OF 5 CA'S RESOLVED SEE ATTACHED LOCATION PICTURES AND NOTES	garcia-cr1	05/21/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404668726	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7556539
719002052	FOLLOW UP LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7556538