

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2026

Submitted Date:

05/21/2026

Document Number:

721100411

**FIELD INSPECTION FORM**

Loc ID 443658 Inspector Name: Blair, Jamie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Findings:**

- 20 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Mach NR/Simcoe		ehsinspections@machnr.com	
Blair, Jamie		jamie.blair@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443655	WELL	PR	12/01/2021	CBM	067-09956	Ford H 1	PR
443657	WELL	PR	05/12/2022	CBM	067-09958	Ford H 3	PR

**General Comment:**

ON Thursday, May 14, 2026, Southwest Compliance Inspection Jamie Blair performed a compliance inspection and audit. There are two active wells on the location which is immediately adjacent to a single well location operated by another operator. Corrective actions pertaining to unused equipment, unmarked risers, stained soil and debris. Photos included as link in attachment section.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Label is peeling off, but still legible. Label should be replaced soon to remain in compliance with 605.h.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	by pad entrance. Both wells on single sign. Photo 1. Operator no longer legible.		
Corrective Action:	Comply with 605.	Date:	06/22/2026

Emergency Contact Number:

Comment:	24 hour 970-247-6919 emergency = 911	Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:	liner or absorbant liner material in well cellar is cracked and blowing out of cellar is on ground nearby.		
Corrective Action:	Comply with 606	Date:	06/22/2026
Type	UNUSED EQUIPMENT		
Comment:	Heat shields or safety guards. Photo 14.		
Corrective Action:	Remove or return to service to comly with 606.	Date:	06/22/2026

Overall Good:

**Spills:**

Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	cathodic protection		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 0		
Comment:			

Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	wellheads		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	solar telemetry		
Corrective Action:		Date:	
Type: Flow Line	# 4		
Comment:	for each well: 3 inch well nipples down to 2 inch toe meter run with various valves to meter run. Single meter run shed. 2 2" pipes leave meter house, nipples up to 3 inch dogleg to offsite. 3/8" stainless tube from well to meter run to 6x6 foot valve/regulator box. 1" line to take well gas to prime mover.		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	lube oil contains on spill prevention at each pumpjack.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	single shed, 2 meters. Cal dates 7/23//25		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	well gas. Operating.		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	2 6 by 8 foot box with electric conduit and 3/8 stainless tube entering. Contains various valves and regulators.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		37.102097,-107.707792
Comment:	label is peeling. Still legible, but not for long.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 443655 Type: WELL API Number: 067-09956 Status: PR Insp. Status: PR

**Producing Well**

Comment: pr

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/11/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 6 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 443657 Type: WELL API Number: 067-09958 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/11/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 7 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Ditches	Pass					
Waddles	Pass	Waddles	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Areas with wattles appears stabile and without visible erosion in some places, straw wattles are deteriorating and have sunken into soil in others. Operator should determine if wattles are still necessary and whether they should be maintained or removed. Removal will cause disturbance, contact SW reclamation specialist if re-seeding is required.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
Corrective actions pertaining to unused equipment, unmarked risers, stained soil and debris. Photos included as link in attachment section. Check with southwest reclamation specialist on status of stormwater BMPs.	blairj1	05/14/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404668694	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7556528">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7556528</a>
721100413	Photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7556527">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7556527</a>