

Inspection Photos

API: 061-06480

Operator: MURFIN DRILLING COMPANY INC

Inspection Date: 5/26/2026

County: KIOWA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Center of the location facing north. This area is bare of vegetation and has not been reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:061-06480 | Date: 5/26/2026

Inspection Photos



Photo 2. Center of the location facing south. This area is bare of vegetation and has not been reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 3. Facing southwest at the location. This area is bare of vegetation and has not been reclaimed.



Inspection Photos



Photo 4. West side of the location facing south. This area is bare of vegetation and has not been reclaimed.



Inspection Photos



Photo 5. Facing toward the surrounding undisturbed reference area.

