

# Inspection Photos

API: 061-06590

Operator: OXY USA INC

Inspection Date: 5/26/2026

County: KIOWA



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing south along the former access road. This area is fenced and vegetation is sparse in areas.



## Inspection Photos



**Photo 2.** Facing southeast toward the location.



## Inspection Photos



**Photo 3.** Drone aerial photo facing southeast toward the location. The area at red arrow has not established vegetation.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:061-06480 | Date: 5/26/2026

## Inspection Photos



**Photo 4.** Drone aerial photo facing northwest toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:061-06480 | Date: 5/26/2026


## Inspection Photos



**Photo 5.** Facing northwest overlooking the location.



## Inspection Photos



**Photo 6.** Facing toward the surrounding undisturbed reference area. There are areas in the reference area with sparse vegetation.

