

# Inspection Photos

API: 011-06155

Operator: THOMAS L SPRING LLC

Inspection Date: 5/26/2026

County: BENT



## Inspection Photos



**Photo 1.** The meter flowline riser located along the access road has not been removed.



## Inspection Photos



**Photo 2.** Facing north along the two track road. The vehicle ruts need to be filled in with soil for proper contouring.



## Inspection Photos



**Photo 3.** Facing southeast toward the location. The location has not been reclaimed and there are areas bare of vegetation.



## Inspection Photos



**Photo 4.** West side of the location facing east. The location has not been reclaimed.



## Inspection Photos



**Photo 5.** East side of the location facing west. The location has not been reclaimed.



## Inspection Photos



**Photo 6.** Facing south toward the undisturbed reference area.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:011-06155 | Date: 5/26/2026