

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/27/2026

Submitted Date:

05/31/2026

Document Number:

708909236

FIELD INSPECTION FORM

Loc ID 335074 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
TEP		ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282748	WELL	PR	01/01/2025	GW	045-11823	CHEVRON GM 544-17	PR
282749	WELL	PR	11/01/2021	GW	045-11824	CHEVRON GM 444-17	PR
282750	WELL	PR	10/01/2012	GW	045-11825	CHEVRON GM 344-17	PR
282751	WELL	PR	06/01/2020	GW	045-11826	CHEVRON GM 44-17	PR

General Comment:

This is a Field Inspection/Audit of the scout card, related documents and the location.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Equipment:			
Type: Plunger Lift	# 4		corrective date
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	CHEVRON GM 444-17 well has no form of pressure monitoring equipment located on bradenhead Remaining 3 wells have Taylor plugs located on bradenheads		
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>282748</u>	Type:	<u>WELL</u>	API Number:	<u>045-11823</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>282749</u>	Type:	<u>WELL</u>	API Number:	<u>045-11824</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>282750</u>	Type:	<u>WELL</u>	API Number:	<u>045-11825</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>282751</u>	Type:	<u>WELL</u>	API Number:	<u>045-11826</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Ditches				
		Gravel				Sparse to none in most areas
		Compaction				Small amount of light compaction
Gravel						Sparse to none in most areas
Compaction						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 05/27/2026 at approximately 16:57 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC CHEVRON GM 544-17 Pad Location # 335074 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. While there, I observed normal production operations.</p> <p>Split pad/Remote location - Shared facilities with the CHEVRON MV 25-17 pad location # 335653</p> <p>This is a summary of inspection/audit report.</p>	smelserw	05/31/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708909238	Inspection/Audit 708909236 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7563627