

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/21/2026

Submitted Date:

05/26/2026

Document Number:

713401431

FIELD INSPECTION FORM

Loc ID 316544 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Wilson, Justin		jrwilson@blm.gov	
, TEP		ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284727	WELL	SI	08/01/2025	GW	103-10759	FEDERAL RGU 14-16-198	WK

General Comment:

This is a Field Inspection/audit of the scout card, related documents and the location.
While there, I observed workover operations on FEDERAL RGU #14-16-198 well.
Limited inspection/audit due to ongoing workover operations.

Location

Lease Road:			
	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type OTHER		
Comment:	Rig signs		
Corrective Action:			Date:
	Type WELLHEAD		
Comment:	Sign is weathered & cracking but still legible		
Corrective Action:			Date:
	Type BATTERY		
Comment:	Tank battery sign contains incorrect quarter/quarter section information		
Corrective Action:	Comply with CECMC rule 605		Date: 06/26/2026

Emergency Contact Number:			
	Comment: 970-285-9377/911		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1		
Comment:	Wireline truck		
Corrective Action:			Date:
Type: Ancillary equipment	# 6		
Comment:	Fire extinguishers		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Workover Rig and all associated equipment		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 284727 Type: WELL API Number: 103-10759 Status: SI Insp. Status: WK

Workover

Comment: On 05/21/2026 at approximately 14:35 hours I spoke with consultant Troy Roehm, who advised casing repair operations have been completed; however, a fish remains in the wellbore due to parted tubing.

Refer to document numbers 404542692 & 404649533

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Location lacks compaction and stabilization
Ditches		Compaction				Light compaction
Sediment Traps		Ditches				

Comment: Operator is responsible for maintaining Best Management Practices (BMP's) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: _____

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 05/21/2026 at approximately 14:33 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC FEDERAL RGU#14-16-198 at Location ID #316544 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed workover operations on FEDERAL RGU #14-16-198 well.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <p>1. Signs/Marker - Tank Battery sign contains incorrect quarter/quarter section information with a CA date of 06/26/2026</p> <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	05/25/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404671607	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7558686
713401432	713401431 Inspection-Audit Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7558685