

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/20/2026

Submitted Date:

05/27/2026

Document Number:

719201189

FIELD INSPECTION FORM

Loc ID 312985 Inspector Name: Gaasche, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 95520
Name of Operator: WESCO OPERATING INC
Address: 120 S DURBIN STREET
City: CASPER State: WY Zip: 82602

Findings:

- 6 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dave Weinert		davew@kirkwoodcompanies.com	
Josh Knigge		joshk@kirkwoodcompanies.com	
Parker Coit		parker.coit@wsp.com	
Brian Meidinger		brianm@kirkwoodcompanies.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222715	WELL	PA	01/08/1995	DA	081-06075	MAUDLILN GULCH UNIT 19	RI
223184	WELL	PA	06/19/2020	GW	081-06546	MAUDLIN GULCH UNIT 24	RI
312985	LOCATION	CL			-	MAUDLIN GULCH UNIT-64N95W 35NWSE	RI

General Comment:

On 05/20/2026, NW Reclamation Specialist Emily Gaasche conducted a reclamation inspection at Wesco Operating Inc's MAUDLIN GULCH UNIT-64N95W/35NWSE (Maudlin Gulch #24) location in Moffat County, Colorado.

The location is within CPW High Priority Habitat: Elk Migration Corridor, Elk Production Area.

The following compliance issues were observed during this inspection:

- Fencing around open excavation down
- Trash/debris
- Insufficient wildlife egress

Refer to the Reclamation and Stormwater sections of this report for additional details.

Refer to the photo-documentation attached to this report for additional details.

Any outstanding CA's from previous inspections remain applicable.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unused utility equipment is present at the base of the power pole. Removal is required.		
Corrective Action:	Comply with Rule 606.a.	Date:	06/10/2026
Type	TRASH		
Comment:	Trash/debris, such as wattles in disrepair and t posts, are scattered throughout the location. Removal is required.		
Corrective Action:	Comply with Rule 606.d.	Date:	06/10/2026
Type	OTHER		
Comment:	Wildlife escape ramp appears to be inadequate to prevent wildlife entrapment and egress. Maintenance is required.		
Corrective Action:	Install or repair wildlife protection BMP's to comply with Rule 902.b.	Date:	06/10/2026

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Orange plastic fencing around the open excavation has fallen/is in disrepair. Maintenance is required.		
Corrective Action:	Install or repair wildlife protection BMP's to comply with Rule 902.b.	Date:	06/10/2026

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 222715 Type: WELL API Number: 081-06075 Status: PA Insp. Status: RI

Facility ID: 223184 Type: WELL API Number: 081-06546 Status: PA Insp. Status: RI

Facility ID: 312985 Type: LOCATION API Number: - Status: CL Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Pursuant to Form 6(s) #402438160, the Wesco well was plugged and abandoned on 6/19/2020. Two open remediation projects are occurring at the location; an open excavation is present. No noxious weed issues were observed at the time of inspection, however, ongoing weed monitoring and maintenance is necessary until the location receives a passing final reclamation inspection. Utility equipment is present at the site.

A follow-up inspection will be conducted during future growing seasons to evaluate reclamation progress and compliance with 1004 series Rules.

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404673791	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7560492
719201191	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7560491