

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/20/2026

Submitted Date:

05/27/2026

Document Number:

719201199

FIELD INSPECTION FORM

Loc ID: 312988 Inspector Name: Gaasche, Emily On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 100116

Name of Operator: WOLD OIL PROPERTIES INC

Address: 139 W SECOND ST STE 200

City: CASPER State: WY Zip: 82601

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Josh Knigge		joshk@kirkwoodcompanies.com	
Brian Meidinger		brianm@kirkwoodcompanies.com	
Parker Coit		parker.coit@wsp.com	
Dave Weinert		davew@kirkwoodcompanies.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223189	WELL	PA	07/10/2009	DA	081-06551	GOV'T-STROOCK-NCT-1 4	RI

General Comment:

On 05/20/2026, NW Reclamation Specialist Emily Gaasche conducted a reclamation inspection at Wesco Operating Inc's GOV'T-STROOCK-NCT-1-64N95W/35NENE (Gov't Strook #1-4) location in Moffat County, Colorado. The location is Fed Surface. Location ownership was updated in COGIS to Wesco Operating Inc; per doc. #404264338, Wesco utilized the location as a landfarm. Weco is the last Operator at this Location and responsible for future reclamation efforts.

The location is within CPW High Priority Habitat: Elk Migration Corridor, Elk Production Area.

The following compliance issues were observed during this inspection:

- Noxious weeds and undesirable plant species
- Perimeter fencing in disrepair

Refer to the Location, Reclamation and Stormwater sections of this report for additional details.

Refer to the photo-documentation attached to this report for additional details.

Any outstanding CA's from previous inspections remain applicable.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:					
Type	OTHER				
Comment:	Perimeter fencing around the location is in disrepair/down in some places. Maintenance is required.				
Corrective Action:	Maintain/repair perimeter fencing.			Date:	06/27/2026

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 223189 Type: WELL API Number: 081-06551 Status: PA Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Two well markers are present. The location has been bermed and pocked; vegetation throughout the location is well-developed with rubber rabbitbrush, Great Basin wildrye, clover, big sagebrush and common dandelion. Undesirable and noxious weed species such as houndstongue, hoary cress, purple mustard, annual weedy mustard species, cheatgrass and thistle is present throughout the location. Weed control is required.

See ECMC Comments section for additional Reclamation details.

Corrective Action: **Comply with Rules 606.c. and 1004.e.**

Date _____

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

ECMC Comments

Comment	User	Date
<p>Additional Reclamation Comments:</p> <p>Pursuant to document #1947151, the 05-081-06551 well was plugged and abandoned in 2009 by Wold Oil. Documentation indicates that the 05-081-06069 was plugged and abandoned by Texaco in 1980 (document #159314). Location ownership updated to Wesco Operating; Per doc. #404264338, Wesco utilized the location as a landfarm. Wesco is the last Operator at this Location and responsible for future reclamation efforts.</p> <p>The location has not been reclaimed pursuant to 1004 series rules; this location is on BLM land (Federal Surface). Location remains subject to 1004 requirements, however final passing by the ECMC is subject to Federal Approval. For any work to be done, or not done, in a manner that does not comport with ECMC rules, Operator shall provide signed documentation showing approval by the BLM; documentation shall be attached to a Form 4 Sundry Notice for ECMC Reclamation Staff review.</p> <p>The Operator has indicated that they plan to remove the perimeter berm and provide documentation from the BLM regarding final reclamation at the location. The access road will be reclaimed and reseeded. Overall Final Reclamation status is left blank and a follow-up inspection will be conducted during future growing seasons to assess 1004 reclamation efforts on the access road and at the location.</p>	gaaschee	05/27/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404674813	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7561168
719201200	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7561167