

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/24/2026

Submitted Date:

06/04/2026

Document Number:

721100430

FIELD INSPECTION FORM

Loc ID 333575 Inspector Name: Blair, Jamie On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10679
Name of Operator: LOGOS OPERATING LLC
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87401

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 22 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
General		Regulatory@logosresourcesllc.com	SJB inspect
Blair, Jamie		jamie.blair@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214365	WELL	PR	04/01/2015	GW	067-05775	BONDAD 33-10 24	PR

General Comment:

On Monday 05/18/2026 at 10:20 AM and Wednesday, 05/27/26 at 13:30 PM, southwest compliance specialist Jamie Blair performed a complinace inspectin and audit of this well location. The well is located within the FEMA floodplain of the Animas River. Corrective actions were identified. Photos are linked in the attachments section of this report along with a map from the FEMA Floodplain website.

Location			
Lease Road:			
Type	Access		
comment:	Cuts through rural subdivision near highway, base is predominantly hard natural river gravel with minor seasonal rutting.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Sign next to unlocked gate (south side of road) on access route (shared with houses) by intersection with HWY 550. Photo 2.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Sign on wellhead. Lettering for emergency contact is small and beginning to peel. It will no longer be in compliance with 605 once if peeling soon. Photo 1.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	New tank with new plastic lined secondary containment. Lacks signage of any kind. Photo 9, 15.		
Corrective Action:	Install signs/labels/placards per rule 605.h.		Date: 06/05/2026
Emergency Contact Number:			
Comment:	Emergency contact 899-598-6220 or 911. Will not remain legible for much longer.		
Corrective Action:			Date:
Good Housekeeping:			
Type	WEEDS		
Comment:	Vegetation growing within production areaa includes cheat grass, kochia, and russian thistle. Dead vegetative debris near heated separator. Potential fire risk. Photo 15, 16, 17.		
Corrective Action:	Remove a miniumum of 25 feet from wellhead(s), tanks, and separators to comply with 610.k		Date: 06/15/2026
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:	11/10/25 cal. date. Photo 14.		

Corrective Action:		Date:	
Type: Other	# 1		
Comment:	wellhead.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	on heated separator stack.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:	4 marked, one unmarked near tank. Photo 10.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	accessible.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Solar Telemetry in NW corner with electrical control panel and on meter run.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:	1) Skid mounted. In FEMA flood plain, doe not appear to be anchored. Photo 18. 2) Concrete pad at separator location, no form 27. Photo 11, 12.		
Corrective Action:	1) Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 421.b.(2). 2) Submit form 27 per 913.c.(9) for removed separator.		Date: <u>07/03/2026</u>
Type: Flow Line	# 1		
Comment:	2" wellhead to separator, 2" to separator to meter run with above ground section on concrete pad at what looks like old meter run or separator location. 2" dump line from separator to tank. 1" flow line, with cut off, open end, sticks up 3 feet. Not marked or tagged. Photo 12.		
Corrective Action:	Apply OOSLAT to comply with Rule 1105.b.		Date: <u>07/03/2026</u>

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		37.056713,-107.879659
Comment:	Newer tank with galvanized metal secondary containment with HDPE Liner. Is in FEMA flood plain. Not anchored. No signs or labeles (see signs tab for CA). Photo 9, 15, 17.				
Corrective Action:	1) Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 421.b.(2). 2) Inpsect and maintain tank per 609.b.				Date: <u>07/03/2026</u>

Paint

Condition	Adequate
Other (Content)	Unknown. Contents not labeled
Other (Capacity)	Unknown.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	<p>Newer metal berm with HDPE liner. Had 4 inches of discolored fluid inside on 5/18. Photo 9, 15, 17.</p>				
Corrective Action:	<p>Maintain secondary containment by removing discolored fluid and disposing as waste according to 905.a.</p> <p>Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 421.b.(2). (30 Days)</p>			Date:	07/03/2026

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 214365 Type: WELL API Number: 067-05775 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/06/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: accessible

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Is in FEMA floodplain of Animas River. Seasonal rutting on production area. Recent grading of soil in area between wellhead and meter run.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Corrective actions identified for equipment anchoring in floodplains, tank signage, waste in secondary containment, weeds/vegetative debris, flow line risers not in use.	blairj1	05/27/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
721100432	FEMA Floodplain Map of Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7567591
721100438	Inpsection Photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7567592