

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/26/2026

Submitted Date:

05/26/2026

Document Number:

716302360

**FIELD INSPECTION FORM**

Loc ID 321227 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC  
Address: 992 S 4TH AVE SUITE 100-461  
City: BRIGHTON State: CO Zip: 80601

**Findings:**

- 12 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
L, Stacy		stacy@strachanexploration.com	Field inspections
Harms, Jason		Jason@strachanexploration.com	Strachan Exploration

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206353	WELL	PR	12/01/2025	GW	011-06100	ROWE A 1	PR

**General Comment:**

"This is a field audit of the scout card, related documents and the location."

<b>Location</b>			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type			
Comment:	PHOTO 2: WELL SIGN STATES WELL IS IN KIOWA COUNTY, ECMC RECORD SHOWS WELL IS IN BENT COUNTY.		
Corrective Action:	POST SIGN TO COMPLY WITH RULE 605.		Date: <u>06/26/2026</u>
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		
Date: _____			
<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:	PHOTO 6: TRASH (RAGS ON GROUND NEAR TANK BATTERY BERM AT ENTRANCE OF LOCATION). PHOTO 7: TRASH (OLD INSULATION INSIDE METER HOUSE).		
Corrective Action:	REMOVE ALL TRASH IN AND AROUND LOCATION PER RULE 606.		Date: <u>06/26/2026</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	PHOTO 8: FENCE IS DOWN ON BACKSIDE OF TANK BATTERY.		
Corrective Action:	REPAIR FENCE PER RULE 606.		Date: <u>06/26/2026</u>
<b>Equipment:</b>			
			corrective date
Type: Other	# 2		
Comment:	SPILL KITS		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	PHOTO 9: ANNUAL METER CALIBRATION PAST DUE.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date: <u>06/26/2026</u>

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	STEEL AST		38.198886,-102.745944

Comment:	
Corrective Action:	Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	210 BBL
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 206353 Type: WELL API Number: 011-06100 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 12/26/2025 Annual Brhd Completed?           

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: FORM 17 IS ON FILE DOC. #404488617

Corrective Action:

Date:

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: 

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

### ECMC Comments

Comment	User	Date
<p style="color: blue; margin: 0;"> <a href="#">ECMC Inspection Report Summary</a>            Date: 5/26/2026            Time: 09:49            Operator: STRACHAN EXPLORATION INC 83130            Location: ROWE No. 1            API# 05-011-06100            County: KIOWA            While there, I ECMC staff performed a field audit of the scout card, related documents and the location. During the audit the following possible compliance issues were observed:            TRASH NEAR TANK BATTER &amp; IN METER HOUSE, RULE 606, CA DATE 6/26/2026.            TANK BATTERY FENCE DOWN, RULE 606. CA DATE 6/26/2026, GAS METER ANNUAL CALIBRATION, rule 430.d.(1). CA DATE 6/26/2026. A follow-up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.         </p>	beardslt	05/26/2026

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404677505	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7563246">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7563246</a>
716302363	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7563241">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7563241</a>