

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/26/2026

Submitted Date:

06/01/2026

Document Number:

719501164

**FIELD INSPECTION FORM**

Loc ID 322401 Inspector Name: Morris, Matthew On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

17 Number of Comments

5 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 10844

Name of Operator: QB ENERGY OPERATING LLC

Address: 1001 17TH STREET SUITE 1600

City: DENVER State: CO Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210414	WELL	IJ	03/01/2026	DSPW	045-06170	LW FEDERAL DISPOSAL 1	IJ

**General Comment:**

This is a field audit of the location, scout card, and related documents.

On 5/26/2026 at approximately 12:40, Compliance Inspector Matthew Morris conducted an on-site audit at QB ENERGY OPERATING LLC, LW FEDERAL DISPOSAL-68S97W/6SENE at Location ID #322401 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign observed.		
Corrective Action:	Comply with CECMC Signage Requirements.	Date:	07/02/2026

Emergency Contact Number:

Comment: 911/(970)285-2615

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused chemical tank near pump house.		
Corrective Action:	Remove unused equipment from location.	Date:	06/09/2026
Type	WEEDS		
Comment:	Weeds present in and around storage tank secondary containment.		
Corrective Action:	Remove weeds from location.	Date:	06/09/2026

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	Concrete barrier installed at pump house.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Chain link fencing		
Corrective Action:		Date:	
Type	WELLHEAD		

Comment:	Concrete barriers		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Concrete barriers		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Trash bins		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Truck offloading station.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Heavy equipment; grader		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Injection pump. Door to pump housing is damaged and poses a wildlife entry hazard.		
Corrective Action:	Secure equipment to prevent wildlife entry.		Date: 06/09/2026
Type: Other	# 1		
Comment:	Door for electrical housing is damaged and poses a wildlife entry hazard.		
Corrective Action:	Secure equipment to prevent willife entry.		Date: 06/09/2026

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	7	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 210414 Type: WELL API Number: 045-06170 Status: IJ Insp. Status: IJ

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
(e.g. 30 psig or -30" Hg) Inj Zone: WMFK  
TC: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ Last MIT: 10/21/2022  
Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: Routine UIC Inspection.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: PUMP FEED

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams				
Compaction						
		Gravel				
				Material Handling And Spill Prevention		
		Ditches				
Gravel						
		Culverts				
		Compaction				
Berms						
				Spill Response		

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <p>1) No battery sign observed                      2) Weeds in and around secondary containment                      3) Unused equipment                      4) Wildlife entry hazards at pump housing and electrical housing</p> <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morrism	06/01/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404679706	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7565040">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7565040</a>
719501165	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7565039">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7565039</a>