Type UNUSED EQUIPMENT Comment: Unused muffler equipment at pumpjack and cable debris in the western portion of the interim reclamation area.

Removed unused muffler equipment at pumpjack and cable debris in the western portion of the interim reclamation area.

Type OTHER Comment: Stained soils/small spill observed at pumpjack.

Repaired leaks and removed stained soil and disposed of it properly.

Comment Unmarked guy line anchors throughout the active pad

Marked guy line anchor.

Comment: Erosion observed forming in the southern portion of the pad, no stormwater BMPs were observed. Additional tunnel erosion observed on the western edge berm. Future revegetation efforts may be needed in the southern interim reclamation areas.

All erosion issues have been addressed properly.