
Schlumberger
Array Induction Imager Tool
Gamma Ray
Caliper
Bit Size
Deep Induction
Medium Induction
Shallow Induction
Spherically Focused Resistivity
Rt
Rxo
Rm
Rmf
Rmc
Delta Rho
Neutron Porosity
Density Porosity
Photoelectric Factor
Pe
Rhob
Drho
Corr
Delta T
Mud Type
Mud Density
Mud Resistivity
Mud Filtrate Resistivity
Mud Cake Resistivity
Source of Sample
Rm @ BHT
Time Since Circulation
Max Recorded Temperature
Equipment Number
Location
Recorded By
Witnessed By
Run Number
Depth Driller
Depth Logger
Bottom Logged Interval
Top Logged Interval
Casing Driller
Casing Logger
Bit Size
Type Fluid in Hole
Density
Viscosity
pH
Fluid Loss
Source of Sample
Rm @ Measured Temperature
Rmf @ Measured Temperature
Rmc @ Measured Temperature
Source of Rmf and Rmc