

NOTES

GPS OPERATOR MARK BESSIE
OBSERVED A PDOP OF 2.4.
ALL GPS OBSERVATIONS ARE IN
COMPLIANCE WITH COGCC RULE No.215.

SURVEYOR'S STATEMENT

I, RICHARD A. BULLEN JR., AN EMPLOYEE AND AGENT ON BEHALF OF D.R. GRIFFIN & ASSOCIATES, INC. STATE THE PLAT HEREON IS A CORRECT REPRESENTATION OF A SURVEY MADE UNDER MY SUPERVISION ON OCTOBER 2, 2008 OF THE SHOWN FEDERAL RGU 23-25-198 AS STAKED ON THE GROUND.
FIELD SURVEY DATUM IS NAD 27 COLORADO NORTH. VALUES HAVE BEEN CONVERTED TO NAD 83 COLORADO CENTRAL (X,Y) FOR PURPOSES OF THIS PLAT.

COLORADO REGISTERED PROFESSIONAL LAND SURVEYOR
RICHARD A. BULLEN JR.
28647
1/13/11

Richard A. Bullen Jr.
COLORADO P.L.S. No. 28647

LEGEND

- ◈ WELL LOCATION
- ☐ BOTTOM HOLE LOC. (APPROX)
- ● FOUND MONUMENT
- ▲ PREVIOUSLY FOUND MONUMENT

RGU 32-25-198 PAD

DRG GRIFFIN & ASSOCIATES, INC.
(307) 362-6026
1414 ELK ST., ROCK SPRINGS, WY 82901

PLAT OF DRILLING LOCATION FOR WILLIAMS PRODUCTION RMT COMPANY

DRAWN: 1/30/09 - MMM	SCALE: 1" = 1000'
REVISED: 1/13/11 - DEH	DRG JOB No. 14646
MISC. REVISIONS	PLAT 1

2199' F/NL & 1761' F/EL, SWNE, SECTION 25,
T. 1 S., R. 98 W., 6th P.M.
RIO BLANCO COUNTY, COLORADO