FORM 22 Rev 6/99

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109

FOR OGCC USE ONLY

ACCIDENT REPORT

As required by Rule 602.b.

Report taken by:

DESCRIPTION OF ACCIDENT (Please be as specific as possible)

Name of Operator: PDC ENERGY
Date of Incident: 4/3/2011
Type of Facility (well, tank battery, flow line, pit): PAD FACILITY (MESA 13)
Well Name and Number: PUCKETT 12A-7D
API Number: 05045155240000
Connect to Accident (land owner, royalty owner, etc).:

Location

County: GARFIELD
Field Name: PICEANCE
QtrQtr: Section: 36
Township: 6S Range: 97W
Meridian:

Provide a detailed description of the accident, problem, and cause (equipment failure, human error, etc.):

Pumper drove from PDC Energy office in Parachute Colorado to the Mesa 13 pad facility. Pumper observed the separator to be charred from a flash fire. Pumper notified supervisor of the incident. Investigation was performed by PDC Energy InvestigationTeam. Cause of the fire was found to be a partially opened half-inch ball valve. The valve is located on the outside of the production unit housing close to the units burner chamber. Ignition source is thought to be either the pilot or main burner on the unit. It is suspected that the valve was opened by an animal. The valve has since been positioned in such a way that it cannot be opened by animals rubbing up against it. Approximately $20,000 damage was incurred to the separator.

OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact Person	Response

Accident Tracking No: