CEMENTER'S WELL SERVICE, INC.

P.O. BOX [illegible] · GREELEY, CO 80633 · (970) 353-7299 · FAX (970) 353-7712

RECD EUSD

OCT 28 2010

5-646

OUR INVOICE

198505

(PO.#79529)

Date 10-14-10	Well Owner PDC.	Well No. 22-ND	Lease BAUER DE BUS
County WELD	State COLORADO		Field
Charge to ENSIGN US DRILLING			Charge Code
Address PO BOX 17805 (ENSIGN-5)			For Office Use Only
City, State DENVER COLORADO 80217			

Pump Truck No. 1202	Code	Bulk Truck No. 1216/1217	Code		
Type of Job		Depth	Ft. 706		To
Surface 8 5/8" CSG-24#		Bottom of Surface	Ft. 696		To
Plug		Plug Landed @ 653	Ft.	Time On 2315	
Production		Pipe Landed @ 696	Ft.	Time Off PLUG DOWN 0145	

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat ✓	490	SKS		
	Poz. Mix				
	Calcium Chloride	3%			
	Gel % Flo-Cele #Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				
	MIX RATE 4 BPM	SLURRY VOL	1.18	FT³/SK	
	DISP. RATE 5 BPM	SLURRY WT	15.2	PPG	
	PLUG LANDED @ 700 PSI	TOTAL SLURRY VOL	103	BBL	
		WATER TEMP	60 °F		

Remarks:	Tax Reference Code	Sub Total
PRE-FLUSH W/ 20 BBL H2O		
DISPLACE 41.5 BBL H2O	State CO 2.9 %	Tax
CIRCULATE 5 BBL CEMENT	Disc.	Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other
1202		Pump Truck		18		
1216/1217		Bulk Truck		18		

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to revicv

Delivered By JOE, JOSH, KERRY

Received By _____ Customer or His Agent