32

CEMENTER'S WELL SERVICE, INC.

P.O. BOX 338220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

198700

(P.O.# 89418)

Date 11-28-10	Well Owner PDC	Well No. 22-10DU	Lease BINDER
County WELD	State COLORADO		Field
Charge to ENSIGN US DRILLING			Charge Code
Address PO BOX 17805 (ENSIGN-32)			For Office Use Only
City, State DENVER COLORADO 80217			

Pump Truck No. 1202	Code	Bulk Truck No. 1217	Code		
Type of Job		Depth	Ft. 435		To
Surface 8 5/8" CSG-24#		Bottom of Surface	Ft. 424		To
Plug		Plug Landed @ 409	Ft.	Time On 2300	
Production		Pipe Landed @ 424	Ft.	Time Off PLUG DOWN 0045	

Reference No.	Description	Qty.	Meas.	Unit Pr
	Pump Truck Charge			
	Cement Neat ✓	300	SKS	
	Poz. Mix			
	Calcium Chloride	3%		
	Gel % Flo-Cele #Per Sack			
	Handling Charge			
	Hauling Charge			
	Additional Cement			
	SLURRY VOL 1.18	FT^3/SK		
MIX RATE 4 BPM	SLURRY WT 15.2	PPG		
DISP. RATE 5 BPM	TOTAL SLURRY VOL	63	BBL	CEMEN
PLUG LANDED @ PSI	WATER TEMP 46	°F		

Remarks:
PREFLUSH W/ 15 BBL H2O
DISPLACE W/ 26 BBL H2O
CIRCULATE 5 BBL CEMENT

Tax Reference Code	Sub Total
State CO 2.9%	Tax
Disc.	Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming
1202		Pump Truck		36	
1217		Bulk Truck		36	

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject t

Delivered By JOE, JOSH, KERRY, CUAN

Received By Jim Filiner
Customer or His Agent