5-679

CEMENTER'S WELL SERVICE, INC.

P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

199702

(P.O # 122916)

Date 4/17/11	Well Owner PDC	Well No. 23-32D	Lease Nelson
County Weld	State Colorado		Field
Charge to ENSIGN US Drilling			Charge Code
Address P.O Box 17805 (ENSIGN #5)			For Office Use Only
City, State Denver Colorado 80217			

Pump Truck No. 1208	Code	Bulk Truck No. 1214/1217	Code		
Type of Job		Depth	Ft. 948		To
Surface 8 5/8" CSG-24#		Bottom of Surface	Ft. 938		To
Plug		Plug Landed @ 895	Ft.	Time On 1055	
Production		Pipe Landed @ 938	Ft.	~~Time Off~~ Plug Down 1245	

Reference No.	Description	Qty.	Meas.	Unit
	Pump Truck Charge			
	Cement Neat ✓	1600	SKS	
	Poz. Mix			
	Calcium Chloride	3%		
	Gel % Flo-Cele 1/4 #Per Sack			
	Handling Charge			
	Hauling Charge			
	Additional Cement			
	Mixing Rate - 4 BPM / Displacement Rate - 4 BPM			
	Slurry Vol - 1.18 Cu FT/SK - Slurry WT 15.2 PPG			
	Total Slurry Vol 138.5 BBLS Cement			
	Landed Plug @ 400 PSI / Water Temp 59° F			

Remarks: Pre-Flush w/ 30 BBLS H^{20}	Tax Reference Code	Sub Total
Displace w/ 57 BBLS H^{20}	State CO 2.9 %	Tax
Circulate 60 BBLS Cement	Disc.	Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming
1208		Pump Truck		60	
1214/1217		Bulk Truck		60/60	

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By Justin Dallas Justin - Oscar

Received By _____ Customer or His Agent