CEMENTER'S WELL SERVICE, INC.

P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

200265

Date 11/19/11	Well Owner Baywater Exploration	Well No. 17-22	Lease Herrell
County Weld	State Colorado		Field
Charge to Baywater Exploration & Production, LLC			Charge Code
Address 730 17th Street, Suite #610 (Ashby #1)			For Office Use Only
City, State Denver, Colorado 80202			
Pump Truck No. 208	Code	Bulk Truck No. 1207/1217	Code
Type of Job		Depth Ft. 867	To
(Surface) 8 5/8" CSG - 24#		Bottom of Surface Ft. 855	To
Plug		Plug Landed @ 813 Ft.	Time On 0750
Production		Pipe Landed @ 855 Ft.	~~Time Off~~ Plug Down 1215

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat ✓ 100% Excess	1600	SKS		
	Poz. Mix				
	Calcium Chloride	3%			
	Gel % Flo-Cele ¼ #Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement TOP JOB	40	SKS	14.85	

Mix Rate 4	BPM	Slurry Vol - 1.18 FT³/SK - Water Temp	48°F	
Disp Rate 4	BPM	Slurry WT 15.2 PPG		
Plug landed @ 600 PSI		Total Slurry Vol - 134.5 BBLS Cement		

Remarks: Pre-Flush w/ 30 BBLS H20	Tax Reference Code	Sub Total
Displace w/ 51.7 BBLS H20	State CO 2.9 %	Tax
Circulate 0 BBL Cement	Disc.	Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other
208		Pump Truck		30		
1207/1217		Bulk Truck		30/30		

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By Justin, Kenny & Demetrio

Received By Terry L Chapman - PEMI
Customer or His Agent