CEMENTER'S WELL SERVICE, INC.

P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

200148

Date 9/17/11	Well Owner Baysuwater Exploration	Well No. 15-22	Lease IRVINE
County Weld	State Colorado		Field
Charge to ~~Ashby Drilling Corporation~~ Baysuwater			Charge Code
Address P.O. Box 19978 (Ashby Rig #1)			For Office Use Only
City, State Boulder, Colorado 80303			

Pump Truck No. 1208	Code	Bulk Truck No. 917/1218	Code		
Type of Job		Depth	Ft. 780		To
(Surface) 8 5/8" CSG - 24#		Bottom of Surface	Ft. 767		To
Plug		Plug Landed @ 725	Ft.	Time On 1350	
Production		Pipe Landed @ 767	Ft.	~~Time Off~~ Plug Down 1745	

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat ✓	540	SKS		
	Poz. Mix				
	Calcium Chloride	3%			
	Gel % Flo-Cele ¼ #Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				
	Mixing Rate - 4 BPM / Displacement Rate - 4 BPM				
	Slurry Vol - 1.18 CU FT/SK - Slurry WT 15.2 PPG				
	Total Slurry Vol 113.4 BBLS Cement				
	Landed Plug @ 400 PSI / Water Temp 62° F				

Remarks: Pre-Flush w/ 30 BBLS H^{20}	Tax Reference Code	Sub Total
Displace w/ 46.1 BBLS H^{20}	State CO 2.9 %	Tax
Circulate 4 BBLS Cement	Disc.	Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other
1208		Pump Truck		34		
917/1218		Bulk Truck		34/34		

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By Justin, Dallas, Kenny & Demetrio

Received By _____ Customer or His Agent