Click here to reset form

FORM 22 Rev 6/99

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109

FOR OGCC USE ONLY

RECEIVED 9/19/2012

Report taken by:

ACCIDENT REPORT

As required by Rule 602.b.

DESCRIPTION OF ACCIDENT (Please be as specific as possible)

Name of Operator: Anadarko Petroleum / Kerr-McGee Oil & Gas Onshore LP
Date of Incident: 9/18/2012
Type of Facility (well, tank battery, flow line, pit): Drilling pad
Well Name and Number: Raymond 38-29 HZ
API Number:
Connect to Accident (land owner, royalty owner, etc).: -104.7961, 40.20245

Location
County: Weld
Field Name: Wattenberg
QtrQtr: NE4 Section: 29
Township: 3N Range: 66W
Meridian:

Provide a detailed description of the accident, problem, and cause (equipment failure, human error, etc.):

At 10:20 in the morning, there was a fire in generator building on Xtreme 8. This resulted in main diesel powered generator being destroyed. The fire apparently started from diesel fuel spraying from a small hole in a fuel recycle line onto the engine/exhaust manifold. The Platteville fire department was called and they responded. Units from Platteville, Ft. Lupton and LaSalle responded. Water from the bulk storage tank on-site was used to cool the other equipment on-site until the flames demiinished in the generator building. There was another rig on the same pad when this fire occurred. All drilling activites were shut down and the crews accounted for. There were no injuries associated with this fire. The drilling rig was located just off CR30, approximately 1.25 miles east of Hwy 85. It is estimated that less than 3 gallons of diesel or oil were spilled. The oil, diesel and cooling water did not leave location and were cleaned up as soon as possible after the fire was out. CR 30 was blocked by the Weld county sheriff's department for a period of time. The fire was out by 11:30 am and traffic was restored.

The COGCC was notified of this incident on 9/1/821 by Terry Clark. He spoke to Margaret Ash on the afternoon the incident occured.

If further information is needed, the Xtreme HSE manager can be reached at.

Larry Carter (larry.carter@xtremecoil.com)

OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact Person	Response

Accident Tracking No:_____