CEMENTER'S WELL SERVICE, INC.

P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

200587

(P.O# 237926)

Date 7/10/12	Well Owner Bayswater Exploration	Well No. 14-22	Lease Ranchero
County Weld	State Colorado		Field
Charge to Ensign US Drilling			Charge Code
Address P.O. Box 17805 (Ensign #7)			For Office Use Only
City, State Denver, Colorado 80217			

Pump Truck No. 1208	Code	Bulk Truck No. 1217/1218	Code	
Type of Job		Depth	Ft. 791	To
Surface 8 5/8" 036-24#		Bottom of Surface	Ft. 776	To
Plug		Plug Landed @ 734	Ft.	Time On 1540
Production		Pipe Landed @ 776	Ft.	~~Time Off~~ Plug Down 1815

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat ✓	550	SKS		
	Poz. Mix				
	Calcium Chloride	3%			
	Gel % Flo-Cele 4 #Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				

Mix Rate	4 BPM	Slurry Vol - 1.18 FT³/SK	Water Temp - 70°F
Disp Rate	5 BPM	Slurry wt 15.2 PPG	
Plug landed @	550 PSI	Total Slurry Vol - 115.5 BBL Cement	

Remarks: Pre-Flush w/ 30 BBL H²⁰
Displace w/ 46.6 BBL H²⁰
Circulate 7 BBL Cement

Tax Reference Code	Sub Total	
State CO 2.9 %	Tax	
Disc.	Total	

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other	Total Mileage
1208		Pump Truck		40			
1217/1218		Bulk Truck		40/40			

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By Justin, Ruben & Steve

Received By _____
Customer or His Agent