State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303)894-2100 Fax:(303)894-2109

SPILL/RELEASE REPORT

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: monument global resorces   OGCC Operator No: 10430

Address: 11260 north abrams road   suite 610

City: dallas   State: tx   Zip: 75243

Contact Person: Kerry Smith 575-937-8001 Tom Fox 970-903-8833

Phone Numbers
No: office 214-691-8846 cell 575-937-8001
Fax:
E-Mail:

DESCRIPTION OF SPILL OR RELEASE

Date of Incident: 6-10-13   Facility Name & No.: monument global resorces well #1

Type of Facility (well, tank battery, flow line, pit): flow line from well #1

Well Name and Number: cache #1

API Number: CS3-F9153

County: montezuma

QtrQtr: _____   Section: 24

Township: _____   Range: _____

Meridian: _____

Specify volume spilled and recovered (in bbls) for the following materials:

Oil spilled: .5   Oil recov'd: 0   Water spilled: 6.5   Water recov'd: 0   Other spilled: _____   Other recov'd: _____

Ground Water impacted? ☐ Yes ☑ No   Surface Water impacted? ☐ Yes ☑ No

Contained within berm? ☐ Yes ☑ No   Area and vertical extent of spill: 180 foot long x 8 foot wide

Current land use: private cattle grasing   Weather conditions: dry /hot

Soil/geology description: sand to clay

IF LESS THAN A MILE, report distance IN FEET to nearest.... Surface water: _____ wetlands: _____ buildings: 450 foot

Livestock: _____ water wells: .5 miles Depth to shallowest ground water: _____

Cause of spill (e.g., equipment failure, human error, etc.): pipe line corrosion   Detailed description of the spill/release incident:

pipe line corrotion under groun d let out aroun 1/2 bbl oil and 6.5 bbls water ran around 180 foot to the southwest and at the widest point around 8 foot

CORRECTIVE ACTION

Describe immediate response (how stopped, contained and recovered):
got a call around 3:45 pm from land owner Cory Veach I drove out to field and shut in wells and all valve leading from wells to tank battery could not see spill at time drove to location and inspected spill at 8:00 am 6-11-13 put down oil hog to mark up any loose oil and water did not recover any oil or water most was soaked up before I arrived

Describe any emergency pits constructed:

How was the extent of contamination determined:
walked out oil spill and used gps to get total length of spill start corr. N 37 x 14.417' x w 109 x 01.498' end corr. 37 x 14.399' x w 01.521'

Further remediation activities proposed (attach separate sheet if needed):
need to reclaim location of spill and also replace pile lines

Describe measures taken to prevent problem from reoccurring:

we have talked with owner and we will check into replacing flow line from well to battery

OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact	Phone	Response
6-11-13	cogc	Karen Spray	1-970-259-1619	work with land owner and get started on clean up
6-11-13	land owner	Cory Veach	1-970-749-0819	got permission to start clean up
6-11-13	loase owner	Kerry Smith	1-575-937-8001	talked about how to repace flow lines

Spill/Release Tracking No: _____

MGR Spill June 2013

1" = 150 Feet

0   75   150   300

N