
Main Pass
Schlumberger
Gamma Ray (GAPI)
Caliper (in)
Bit Size (in)
Neutron Porosity (dec)
Bulk Density (g/cm3)
Photoelectric Factor (b/e)
Delta Rho (g/cm3)
Resistivity (ohm.m)
Deep Resistivity (ohm.m)
Medium Resistivity (ohm.m)
Shallow Resistivity (ohm.m)
Gamma Ray (GAPI)
Caliper (in)
Bit Size (in)
Neutron Porosity (dec)
Bulk Density (g/cm3)
Photoelectric Factor (b/e)
Delta Rho (g/cm3)
Resistivity (ohm.m)
Deep Resistivity (ohm.m)
Medium Resistivity (ohm.m)
Shallow Resistivity (ohm.m)
Gamma Ray (GAPI)
Caliper (in)
Bit Size (in)
Neutron Porosity (dec)
Bulk Density (g/cm3)
Photoelectric Factor (b/e)
Delta Rho (g/cm3)
Resistivity (ohm.m)
Deep Resistivity (ohm.m)
Medium Resistivity (ohm.m)
Shallow Resistivity (ohm.m)
Main Pass
Schlumberger
Gamma Ray (GAPI)
Caliper (in)
Bit Size (in)
Neutron Porosity (dec)
Bulk Density (g/cm3)
Photoelectric Factor (b/e)
Delta Rho (g/cm3)
Resistivity (ohm.m)
Deep Resistivity (ohm.m)
Medium Resistivity (ohm.m)
Shallow Resistivity (ohm.m)
Gamma Ray (GAPI)
Caliper (in)
Bit Size (in)
Neutron Porosity (dec)
Bulk Density (g/cm3)
Photoelectric Factor (b/e)
Delta Rho (g/cm3)
Resistivity (ohm.m)
Deep Resistivity (ohm.m)
Medium Resistivity (ohm.m)
Shallow Resistivity (ohm.m)
Gamma Ray (GAPI)
Caliper (in)
Bit Size (in)
Neutron Porosity (dec)
Bulk Density (g/cm3)
Photoelectric Factor (b/e)
Delta Rho (g/cm3)
Resistivity (ohm.m)
Deep Resistivity (ohm.m)
Medium Resistivity (ohm.m)
Shallow Resistivity (ohm.m)

7700
7800
7900
8000
8100
8200
8300
8400
8500
8600
8700
8800
8900
9000
9100
9200
9300
9400
9500
9600
9700
9800
9900
10000
10100
10200
10300
10400
10500
10600
10700
10800
10900
11000
11100
11200
11300
11400
11500
11600
11700