FORM INSP
Rev X/15

# State of Colorado
# Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

## FIELD INSPECTION FORM

Inspection Date: 08/04/2017
Submitted Date: 08/04/2017
Document Number: 690300012

Loc ID: 316218
Inspector Name: Spencer, Stan
On-Site Inspection: ☐
2A Doc Num:

**Status Summary:**

☒ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

1 Number of Comments
1 Number of Corrective Actions
☒ Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 56680
Name of Operator: MERRION OIL & GAS CORP
Address: 610 REILLY AVENUE
City: FARMINGTON State: NM Zip: 87401

**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---|---|---|---|
| Thompson, Philana | (505) 324-5300 | pthompson@merrion.bz | |
| Lujan, Carlos | | carlos.lujan@state.co.us | |
| Merrion, ryan | (303) 6532231 | ryan@merrion.bz | |
| Granahan, Kyle | | kyle.granahan@state.co.us | |
| Fischer, Alex | | alex.fischer@state.co.us | |

**General Comment:**

## Environmental

**Spills/Releases:**

Type of Spill: CONDENSATE  Estimated Spill Volume: 84

Comment: Followup to Spill#451576. 84 bbl release from tank via subsurface drain line to closed pit. Weather is 90 F and clear. No indications of release on surface. No seeps or odor in dry gulch to the North or at surface of former pit. Trackhoe staged on location but no personnel or activity on site. Per spill report "spill is now contained within the pre-existing pit. A roustabout company was notified to replace the non-freeze valve ASAP and will plug off and disconnect the line running to the closed pit. A plan will be submitted within the next couple days to specify the steps involved to remediate the spill"

Corrective Action: Per COA "Assess nature and extent of soil and/or groundwater contamination withconfirmation samples. Documentation must include a figure showing spill area withsample locations plus laboratory results. Assess and remediate to Table 910-1standards and provide documentation in a either a Supplemental F-19 or F-27. AForm-27 Assessment and Remediation Plan is required if extended remediation isplanned. Any onsite remediation such as landfarming must also be approved bysurface owner (BLM). Any planned remediation other than an immediate "dig andhaul" of contaminated soil to an offsite licensed disposal facility must be preapprovedby COGCC. Documentation must include a figure showing spill area withsample locations plus laboratory results.  Date: 09/30/2017

Reportable: YES  GPS: Lat  Long

Proximity to Surface Water:  Depth to Ground Water:

**Water Well Complaint:**

DWR Receipt Num:  Owner Name:  GPS : Lat  Long

**Field Parameters:**

Sample Location:  Comment:

## Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

| Document Num | Description | URL |
|---|---|---|
| 401365264 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4216913 |
| 690300013 | Looking SE. Former pit was SE of Tank. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4216912 |