Well Name: Tabor 1 **API #** 05-067-06220
Inspection Number: 685200612
Inspection Number: 693900931

Corrective Action: Adequately mark all anchors
Corrective Action: 7/30/2019
Action Completed: Removed anchors.

Corrective Action: Stormwater controls (run-on and runoff) need to be installed to stabilize erosion within the project area by December 21, 2018. Erosion controls such as mulch, hydromulch, or erosion blankets are needed on the well pad cut-slope until vegetation becomes established. This should be installed in coordination with seeding efforts described above
Corrective Action: Installed stormwater controls and erosion controls with hydro mulch and seeding.
Action Completed: 11/18/2019