API No. 103-08716

GETTY-AMOCO #31
NWSW 3 1N 102W 6th PM
RIO BLANCO, CO
Spud date 5/12/1981
not to scale

Information has not been verified.



CURRENT



Proposed procedure:
1) Excavate to at least 4' below grade
2) Cut casings
3) Kill gas flow with water.
4) If cement present contact COGCC engineer and drill out to a depth approved by engineer. Replace cement plugs.
5) If no cement, place surface plug.
6) Install plugging plate.

PROPOSED