
Main Pass
Recorded Mode 3 Wireline Formation Pressure
Run 1 Pass 1
Run 1 Pass 2
Run 1 Pass 3
Run 1 Pass 4
Run 1 Pass 5
Run 1 Pass 6
Run 1 Pass 7
Run 1 Pass 8
Run 1 Pass 9
Run 1 Pass 10
Run 1 Pass