FORM INSP Rev X/20

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

FIELD INSPECTION FORM

Inspection Date: 06/03/2021
Submitted Date: 06/04/2021
Document Number: 690102481

Loc ID: 418782
Inspector Name: Maclaren, Joe
On-Site Inspection: ☐
2A Doc Num:

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments
0 Number of Corrective Actions
☐ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NBLENERGY.COM	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418783	WELL	SI	04/01/2017	GW	123-32007	RAY H 12-24D	EG

General Comment:

COGCC Engineering Integrity Inspection; Flowline Inspection
Photos Uploaded

Inspected Facilities

Facility ID:	418783	Type:	WELL	API Number:	123-32007	Status:	SI	Insp. Status:	EG

Flowline

#1	Type:Non-Well Site	of Lines	

Flowline Description

Flowline Type: Non-Well Site Size: Material:

Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:

Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Well (Ray H 12-24D) is Shut in; OOSLAT observed on off location flowline valves at wellhead and inlet to heated horizontal separator. The shared facility/ battery services (4) wells; other flowlines also observed SI/ OOSLAT at facility/ battery. No Noble Energy personnel were on location at the time of this field inspection.

Corrective Action: Date:

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
690102486	Signage at battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5447270
690102487	Wellhead SI; OOSLAT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5447271
690102488	Flowline SI at HHS; Disconnected OOSLAT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5447272