Inspection Photos

August 25, 2022

<u>Operator</u>: TEP Rocky Mountain LLC - #96850

<u>Location ID</u>: 316596

<u>Location Name</u>: Federal /RGU 23-35-198

<u>Inspection Document #</u>: 702800742

Rio Blanco County, CO

Lot 11 Section 35 T1S R98W

Anna O'Malley
Reclamation Specialist, COGCC

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

8/25/22
+39.919334,-108.361989
245° SW

Photo 1. Photo taken from the east shows an overview of the current working pad area and expansion/construction.

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

8/25/22
+39.918757,-108.363411
52° NE

8/25/22
+39.918771,-108.362464
67° NE

Photo 2. Photo taken from the southeast shows topsoil salvage taking place in the interim areas. Photo also shows a straw wattle installed around the perimeter of the Location.

Photo 3. Refer to Photo 2 comment.

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

Inspection Number: 702800742

8/25/22
+39.919306,-108.361007
230° SW

8/25/22
+39.919306,-108.361007
304° NW

Photo 4. Photo taken from the southeast shows topsoil salvage taking place in the interim areas. Photo also shows a straw wattle installed around the perimeter of the Location.

Photo 5. Refer to Photo 4 comment.

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

8/25/22
+39.919768,-108.361218
174° S

Photo 6. Photo taken from the northeast shows topsoil salvage taking place in the interim areas.

8/25/22
+39.919807,-108.361889
239° SW

Photo 7. Refer to Photo 6 comment.

Photo 8. Photo taken from the southeast shows where the top layer of soil has been removed around the eastern perimeter of the Location.

8/25/22
+39.919246,-108.362708
66° NE

Photo 9. Photo taken adjacent to the wells shows a portable toilet has not been secured to prevent a spill.

8/25/22
+39.918779,-108.366313
67° NE

Photo 10. Photo taken from the western perimeter of the Location shows an overview the proposed pit location.