State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404209285

Date Received:
05/19/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

  1 CA Completed
  0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER   State: CO   Zip: 80202

Contact Name and Telephone:

Name:

Phone: ( )   Fax: ( )

Email:

Additional Operator Contact:

Contact Name	Phone	Email
. QB		ecmc.inspections@qb-energy.com

ECMC <u>INSPECTION SUMMARY</u>:

  FIR Document Number: 707801553

  Inspection Date: 04/16/2025   FIR Submit Date: 04/17/2025   FIR Status:

Inspected Operator Information:

  Company Name: CAERUS PICEANCE LLC   Company Number: 10456

  Address: 1001 17TH STREET #1600

  City: DENVER   State: CO   Zip: 80202

<u>LOCATION</u> - Location ID: 334915

  Location Name: HILL-67S92W   Number: 16SWNW   County:

  Qtrqtr: SWNW   Sec: 16   Twp: 7S   Range: 92W   Meridian: 6

  Latitude: 39.448800   Longitude: -107.678390

<u>FACILITY</u> - API Number: 05-045-   -00   Facility ID: 334915

  Facility Name: HILL-67S92W   Number: 16SWNW

  Qtrqtr: SWNW   Sec: 16   Twp: 7S   Range: 92W   Meridian: 6

  Latitude: 39.448800   Longitude: -107.678390

<u>CORRECTIVE ACTIONS</u>:

1   CA# 204203

Corrective Action: Comply with CECMC Stormwater rules   Date: 02/25/2025

    Response: CA COMPLETED   Date of Completion: 05/16/2025

    Operator Comment: Repaired stormwater erosion.

    ECMC Decision:

	ECMC Representative:	

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Justin Johnson   Signed:

Title: Compliance   Date: 5/19/2025 12:29:13 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (http://ecmcweblink.state.co.us/) - Search by Document Number.

Document Number	Description
404209303	Erosion repaired.

Total Attach: 1 Files