0:00
58.00

Schneider Summit Services
PO Box 983038
Park City, UT 84098

DAILY OPERATIONS REPORT

Date (1st Hour):	05/31/25	**Operator**	**Bison IV Operating**	**Well Name:**	**Guttersen-Kime 1**		
Field:				**Consultant:**	Rusty Tucker / Dave Donoho	**AFE #:**	
County:	Weld			**Phone:**	970-380-2326 / 970-534-0677	**Csg Depth / TD:**	
Operation:	Re-entry P&A			**Rig Contractor:**	Axis #724	**Size / Grade:**	
				Location:		**Weight / Thread:**	
				Lat/Long:		**Perforations:**	

BREAKDOWN OF OPERATIONS

From	To	Hrs	Description
12:00	23:00	11:00	MIRU rig & equipment. Very sandy location, rig got stuck, called for cat, spotted other equipment while waiting for the cat. Racked TBG
23:00	0:59	1:59	TIH w/ 6.25" bit, 6 3.5" DC & TBG. TIH to 400' with out tagging anything.
0:59	0:30	23:31	TOOH. LD bit & DC
0:30	6:00	5:30	TIH w/ muleshoe & 2.875" TBG. CIRC every 5 JTS, 30 JTS in @ 976'
6:00			

TUBING, BHA, Rods

Quantity	OD	ID	Description	Length	Top
			End of Tubing:		

0:00
58.00

Schneider Summit Services
PO Box 983038
Park City, UT 84098

DAILY OPERATIONS REPORT

Date (1st Hour):	06/01/25	**Operator**	**Bison IV Operating**	**Well Name:**	**Guttersen-Kime 1**		
Field:				**Consultant:**	Rusty Tucker / Dave Donoho	**AFE #:**	
County:	Weld			**Phone:**	970-380-2326 / 970-534-0677	**Csg Depth / TD:**	
Operation:	Re-entry P&A			**Rig Contractor:**	Axis #724	**Size / Grade:**	
				Location:		**Weight / Thread:**	
				Lat/Long:		**Perforations:**	

BREAKDOWN OF OPERATIONS

From	To	Hrs	Description
6:00	7:00	1:00	Wash down from 976' to 1,238'
7:00	9:00	2:00	Hang back the power swivel, wash down to 2,054, circulating every 10 JTS
9:00	12:00	3:00	Wash down to 3,428'
12:00	15:00	3:00	Wash down to 4,409'
15:00	18:00	3:00	Wash down to 5420'
18:00	22:30	4:30	Wash down to 6565'
22:30	0:01	1:31	CIRC
0:01	1:00	0:59	RU Axis cementers. Pumped 100 SX 15.8# G cement. Disp w/ mud for balanced plug
1:00	3:00	2:00	TOOH. LD 149 JT. EOT = 1700'
3:00	3:45	0:45	Pumped 50 SX 15.8# G cement Balanced plug
3:45	4:15	0:30	TOOH SB TBG
4:15	6:00	1:45	Wait on cement
6:00			

TUBING, BHA, Rods

Quantity	OD	ID	Description	Length	Top
			End of Tubing:		

0:00
58.00

Schneider Summit Services
PO Box 983038
Park City, UT 84098

DAILY OPERATIONS REPORT

Date (1st Hour):	06/02/25	**Operator**	Bison IV Operating	**Well Name:**	Guttersen-Kime 1		
Field:				**Consultant:**	Rusty Tucker / Dave Donoho	**AFE #:**	
County:	Weld			**Phone:**	970-380-2326 / 970-534-0677	**Csg Depth / TD:**	
Operation:	Re-entry P&A			**Rig Contractor:**	Axis #724	**Size / Grade:**	
				Location:		**Weight / Thread:**	
				Lat/Long:		**Perforations:**	

BREAKDOWN OF OPERATIONS				**TUBING, BHA, Rods**					
From	To	Hrs	Description	Quantity	OD	ID	Description	Length	Top
6:00	8:30	2:30	Wait on cement						
8:30	9:30	1:00	Tag @ 583', LD TBG, muleshoe was full of dehydrated mud. LD TBG from derrick.						
9:30	18:30	9:00	PU bit, 6 drill collars & RIH, hit a few bridges, running 5 JTS & circulating. Tagged cement at 1447'. CIRC clean						
18:30	20:30	2:00	TOOH, LD DC & bit TIH w/ muleshoe. EOT = 519'						
20:30	21:45	1:15	Pumped 200 SX 15.8# G cement/ Did not get cement to surface.						
21:45	22:45	1:00	TOOH & LD TBG						
22:45	6:00	7:15	WOC						
6:00									
							End of Tubing:		

0:00
58.00

Schneider Summit Services
PO Box 983038
Park City, UT 84098

DAILY OPERATIONS REPORT

Date (1st Hour):	06/03/25	**Operator**	**Bison IV Operating**	**Well Name:**	**Guttersen-Kime 1**		
Field:				**Consultant:**	Rusty Tucker / Dave Donoho	**AFE #:**	
County:	Weld			**Phone:**	970-380-2326 / 970-534-0677	**Csg Depth / TD:**	
Operation:	Re-entry P&A			**Rig Contractor:**	Axis #724	**Size / Grade:**	
				Location:		**Weight / Thread:**	
				Lat/Long:		**Perforations:**	

BREAKDOWN OF OPERATIONS

From	To	Hrs	Description
6:00	7:00	1:00	WOC
7:00	7:30	0:30	RIH & tag @ 440'
7:30	8:45	1:15	RU Axis cementers & pump 180 SKS of 15.8# cement w/2% calcium but did not get cement to surface
8:45	9:15	0:30	LD TBG
9:15	12:30	3:15	WOC
12:30	12:50	0:20	RIH & tag @ 247'
12:50	13:15	0:25	RU Axis cementers & pump 95 SKS of 15.8# cement w/2% calcium to surface
13:15	14:00	0:45	LD TBG, top off cement @ surface w/ 10 SKS, RD cementers
14:00	16:30	2:30	RDMO rig & equipment
16:30			

TUBING, BHA, Rods

Quantity	OD	ID	Description	Length	Top

End of Tubing:

0:00
58.00

Schneider Summit Services
PO Box 983038
Park City, UT 84098

DAILY OPERATIONS REPORT

Date (1st Hour):	06/11/25	**Operator**	**Bison IV Operating**	**Well Name:**	**Guttersen-Kime 1**		
Field:				**Consultant:**	JAKE SCHNEIDER	**AFE #:**	
County:	Weld			**Phone:**	970-370-1613	**Csg Depth / TD:**	
Operation:	Re-entry P&A			**Rig Contractor:**	Axis #724	**Size / Grade:**	
				Location:		**Weight / Thread:**	
				Lat/Long:		**Perforations:**	

BREAKDOWN OF OPERATIONS

From	To	Hrs	Description
6:00			MIRU RIVAL ROUSTABOUT CREW AND WELDER.
			DIG UP AND CUT OFF CASING 6' BELOW GROUND LEVEL.
			PERFORM BUUBLE TEST. (GOOD TEST)
			WELD ON IDENTIFYING CAP.
			BACK FILL HOLE. RDMO RIVAL ROUSTABOUT CREW AND WELDER.

TUBING, BHA, Rods

Quantity	OD	ID	Description	Length	Top
			End of Tubing:		