OGRIS
OPERATING, LLC

№ 1332

Customer OGris LLC
Well / Lease Ac 14-16V

Date 4-4-25
State CO
Rig No. 1

HOURS	DESCRIPTION
6:30-7:30	travel
7:30-8:30	load up Pipe trailer on to Pick up Drove out
8:30-9:30	to Rig Start Rig Nipple up work head Picked up
9:30-10:30	Rig floor Number And telly Pipe
10:30-1:30	Picked up 50 2 7/8 Joints tagged Plug layed down
	two Joints Shut in Well travel
	tagged Plug at 1587

TOOL BOX SAFETY TOPIC

CHARGE RECORD

Rig Time ____ Hrs @ ____ Per Hr ..... $ ____
Crew Travel x ..... $ ____
Tool Pusher ..... $ ____
Power Rod Tongs x ..... $ ____
Pipe Dope @ $ ____ Per Trip ..... $ ____
Sand Bailers ..... $ ____
Swab Cups ____ # @ $ ____ ..... $ ____
Swab Cups ____ # @ $ ____ ..... $ ____
Oil Svr. Rbr. ____ # @ $ ____ ..... $ ____
Total Charges ..... $ ____

Type Packer ____
No. Jts. Tubing: Size ____
P.B.T.D. ____
No. & Size Rods ____
No. & Size Subs ____
Pump Description Rotor (In) ____ Rotor (Out) ____
Starter (In) ____ Starter (Out) ____
Insert (In) ____ Insert (Out) ____

	RIG	TRAVEL	TOTAL
OPERATOR			
DERRICKMAN			
FLOOR HAND			
FLOOR HAND			

SIGNATURE - SUPERVISOR

SIGNATURE - CUSTOMER REPRESENTATIVE

OGRIS
OPERATING, LLC

№ 1344

Customer Ogris LLC
Well / Lease Ac 14-716 U

Date 4-7-25
State CO
Rig No. 1

HOURS	DESCRIPTION
6:30-7:30	travel
7:30-8:30	Gather supply
8:30-9:30	Started Rig got all cement hoses Rigged up to well head
9:30-10:30	taged Plug at 1587 Pumped cement to 1437
10:30-11:30	laydd Down 8 Joint wait 4 hours
11:30-12:30	Ran in taged top of cement to 1430
12:30-1:30	tripped out the Hole trip in to 262 Set
1:30-2:30	CIBP Pump cement to Surface tripped out
2:30-3:30	of Hole top off Hole with cement Rig down
	floor and Rig travel

TOOL BOX SAFETY TOPIC

CHARGE RECORD

Rig Time ____ Hrs @ ____ Per Hr. ..... $ ____
Crew Travel x ..... $ ____
Tool Pusher ..... $ ____
Power Rod Tongs x ..... $ ____
Pipe Dope @ $ ____ Per Trip ..... $ ____
Sand Bailers ..... $ ____
Swab Cups ____ # @ $ ____ ..... $ ____
Swab Cups ____ # @ $ ____ ..... $ ____
Oil Svr. Rbr. ____ # @ $ ____ ..... $ ____
Total Charges ..... $ ____

Type Packer ____
No. Jts. Tubing: Size ____
P.B.T.D. ____
No. & Size Rods ____
No. & Size Subs ____
Pump Description Rotor (In) ____ Rotor (Out) ____
Starter (In) ____ Starter (Out) ____
Insert (In) ____ Insert (Out) ____

	RIG	TRAVEL	TOTAL
OPERATOR			
DERRICKMAN			
FLOOR HAND			
FLOOR HAND			

SIGNATURE - SUPERVISOR

SIGNATURE - CUSTOMER REPRESENTATIVE

OGRIS
OPERATING, LLC

№ 1348

Customer Ogris LLC
Well / Lease AC 14-16 V

Date 4-29-25
State CO
Rig No. 1

HOURS	DESCRIPTION
	Drove to location Hooked up 1/4 lines to Anlus + long string
	Well Head. Installed 1/4 Lines in to Buckets of water
	Pre formed Bubble test from 8:30 Am - 9:00 Am
	Bubble test Showed no Signs of leakage. Wipped down
	test equipment. Drove to Yard

TOOL BOX SAFETY TOPIC

CHARGE RECORD

Rig Time ____ Hrs @ ____ Per Hr. ..... $ ____
Crew Travel x ..... $ ____
Tool Pusher ..... $ ____
Power Rod Tongs x ..... $ ____
Pipe Dope @ $ ____ Per Trip ..... $ ____
Sand Bailers ..... $ ____
Swab Cups ____ # @ $ ____ ..... $ ____
Swab Cups ____ # @ $ ____ ..... $ ____
Oil Svr. Rbr. ____ # @ $ ____ ..... $ ____
Total Charges ..... $ ____

Type Packer ____
No. Jts. Tubing: Size ____
P.B.T.D. ____
No. & Size Rods ____
No. & Size Subs ____
Pump Description Rotor (In) ____ Rotor (Out) ____
Starter (In) ____ Starter (Out) ____
Insert (In) ____ Insert (Out) ____

	RIG	TRAVEL	TOTAL
OPERATOR			
DERRICKMAN			
FLOOR HAND			
FLOOR HAND			

SIGNATURE - SUPERVISOR

SIGNATURE - CUSTOMER REPRESENTATIVE