Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad
Location #: 324202

Photo # 5739 From entrance to location

Photo # 5740 Location

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad
Location #: 324202

Photo # 5741 Location

Photo # 5742 Location

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad
Location #: 324202

Photo # 5743 Location

Photo # 5744 Location

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad
Location #: 324202

Photo # 5745 Unused flowline lacks lockout tagout (OOSLAT)



Photo # 5746 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad
Location #: 324202



Photo # 5747 Bradenhead line tied into flowline (line lacks a check valve)

Photo # 5748 Bradenhead line tied into flowline (line lacks a check valve)

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad
Location #: 324202

Photo # 5749 Bradenhead line tied into flowline (line lacks a check valve)

Photo # 5750 Bradenhead line tied into flowline (line lacks a check valve)

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad
Location #: 324202

Photo # 5751 Tubing appears to be shut in & operator is only producing surface casing via bradenhead tie in

Photo # 5752 Tubing appears to be shut in & operator is only producing surface casing via bradenhead tie in

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad
Location #: 324202

Photo # 5753 Tubing appears to be shut in & operator is only producing surface casing via bradenhead tie in

Photo # 5754 Tubing appears to be shut in & operator is only producing surface casing via bradenhead tie in

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad
Location #: 324202

Photo # 5755 Tubing appears to be shut in & operator is only producing surface casing via bradenhead tie in

Photo # 5756 Tubing appears to be shut in & operator is only producing surface casing via bradenhead tie in

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad
Location #: 324202

Photo # 5757 Debris