FORM
FIRR
Rev 5/16

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number: 404608122

Date Received: 04/06/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10539

Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP

Address: 734 MAIN STREET 3RD FLOOR

City: GRAND JUNCTION State: CO Zip: 81501

Contact Name and Telephone:

Name:

Phone: ( ) Fax: ( )

Email:

Additional Operator Contact:

Contact Name	Phone	Email
GAS, UTAH		inspections@utahgascorp.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 719501000

Inspection Date: 03/24/2026 FIR Submit Date: 04/01/2026 FIR Status:

Inspected Operator Information:

Company Name: UTAH GAS OP LTD DBA UTAH GAS CORP Company Number: 10539

Address: 734 MAIN STREET 3RD FLOOR

City: GRAND JUNCTION State: CO Zip: 81501

LOCATION - Location ID: 322295

Location Name: SOUTH CANYON-FEDERAL-67S103W Number: 8NWNW County:

Qtrqtr: NWNW Sec: 8 Twp: 7S Range: 103W Meridian: 6

Latitude: 39.473083 Longitude: -108.909519

FACILITY - API Number: 05-045- -00 Facility ID: 322295

Facility Name: SOUTH CANYON-FEDERAL-67S103W Number: 8NWNW

Qtrqtr: NWNW Sec: 8 Twp: 7S Range: 103W Meridian: 6

Latitude: 39.473083 Longitude: -108.909519

CORRECTIVE ACTIONS:

1 CA# 212020

Corrective Action: Secure equipment to prevent wildlife entry. Previous attempt to secure equipment failed; sheet metal screw holding screen has come loose.

Date: 04/07/2026

Response: CA COMPLETED

Date of Completion: 04/03/2026

Operator Comment: Complete

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: 1 CA Completed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tami Dahl Signed:

Title: Production Tech Date: 4/6/2026 7:55:45 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (http://ecmcweblink.state.co.us/) - Search by Document Number.

Document Number	Description
404608122	FIR RESOLUTION SUBMITTED
404608123	Hole Repair

Total Attach: 2 Files