FORM INSP Rev X/20

State of Colorado
Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

FIELD INSPECTION FORM

Inspection Date: 04/27/2026
Submitted Date: 05/05/2026
Document Number: 717000742

Loc ID: 319796
Inspector Name: Finkenbinder, Chane
On-Site Inspection: ☐
2A Doc Num:

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments
0 Number of Corrective Actions
☐ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

ECMC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #225
City: AURORA State: CO Zip: 80016

Contact Information:

Contact Name	Phone	Email	Comment
Espinosa, Bill		billespinosa30@yahoo.com	Inspections
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	All Inspections
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201405	WELL	PR	05/01/2025	OW	001-06808	UPRR 48 PAN AM F 1	PR

General Comment:

This is a field audit of the scout card, related documents, and the location. No Equipment changes since last inspection.

Inspector Name: Finkenbinder, Chane

Location

Overall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action: Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multilple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID:	201405	Type:	WELL	API Number:	001-06808	Status:	PR	Insp. Status:	PR

Producing Well

Comment:	PR		
Corrective Action:		Date:	

BradenHead

Date of Last Brhd Test: 10/14/2024 Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:	Appeared to be plumbed to the surface		
Corrective Action:		Date:	

ECMC Comments

Comment	User	Date
This is a routine field audit of the scout card.	finkenbc	05/05/2026

Attached Documents

You can go to ECMC Images (https://ecmc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
717000743	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7538712