

FORM
17
Rev
6/99

State of Colorado

Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:
402499305

BRADENHEAD TEST REPORT

Step 1. Record all tubing and casing pressures as found. Step 2. Sample now. If intermediate or surface casing pressure > 25 psi. In sensitive areas, 1 psi.
Step 3. Conduct Bradenhead test. Step 4. Conduct intermediate casing test. Step 5. Send report to BLM within 3 days and to ECMC within 10 days. Include wellbore diagram if not previously submitted or if wellbore configuration has changed since prior program. Attach gas and liquid analyses if sampled.

1. ECMC Operator Number: 69175 3. BLM Lease No: _____
 2. Name of Operator: PDC ENERGY INC
 4. API Number; 05-123-47664-00 5. Multiple completion? Yes No
 6. Well Name: Bost Farm Number: 4C-11-L2
 7. Location (QtrQtr, Sec, Twp, Rng, Meridian): SWNW,7,5N,66W,6
 8. County WELD 9. Field Name: DJ HORIZONTAL CODELL
 10. Minerals: Fee State Federal Indian

11. Date of Test: 09/20/2020
 12. Well Status: Flowing
 Shut In Gas Lift
 Pumping Injection
 Clock/Intermitter
 Plunger Lift
 13. Number of Casing Strings:
 Two Three Liner?

14. EXISTING PRESSURES

Record all pressures as found	Tubing: <u>1160</u> Fm: _____	Tubing: _____ Fm: _____	Prod Csg <u>1436</u> Fm: _____	Intermediate Csg: _____	Surf. Csg <u>121</u>
-------------------------------	----------------------------------	----------------------------	-----------------------------------	----------------------------	-------------------------

BRADENHEAD TEST

Buried valve? Yes No
 Confirmed open? Yes No
 With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals Define characteristics of flow in "Bradenhead Flow" column using letter designations below:
 O = No Flow; C = Continuous; D = Down to 0; V = Vapor
 H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas

BRADENHEAD SAMPLE TAKEN?
 Yes No Gas Liquid
 Character of Bradenhead fluid: Clear Fresh
 Sulfur Salty Black
 Other:(describe) _____
 Sample cylinder number: _____

Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermedia Csg PSIG	Bradenhead Flow:
00:00	<input type="checkbox"/> 1160	<input type="checkbox"/>	<input type="checkbox"/> 1436		
05:00	<input type="checkbox"/> 1160	<input type="checkbox"/>	<input type="checkbox"/> 1436		CONTINUOUS
10:00	<input type="checkbox"/> 1160	<input type="checkbox"/>	<input type="checkbox"/> 1436		CONTINUOUS
15:00	<input type="checkbox"/> 1160	<input type="checkbox"/>	<input type="checkbox"/> 1436		DOWN TO 0
20:00	<input type="checkbox"/> 1160	<input type="checkbox"/>	<input type="checkbox"/> 1436		NO FLOW
25:00	<input type="checkbox"/> 1160	<input type="checkbox"/>	<input type="checkbox"/> 1436		NO FLOW
30:00	<input type="checkbox"/> 1160	<input type="checkbox"/>	<input type="checkbox"/> 1436		NO FLOW

Instantaneous Bradenhead PSIG at end of test: > 0

INTERMEDIATE CASING TEST

Buried valve? Yes No
 Confirmed open? Yes No
 With gauges monitoring production, intermediate casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals Characterize flow in "Intermediate Flow" column using letter designations below:
 O = No Flow; C = Continuous; D = Down to 0; V = Vapor
 H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas

INTERMEDIATE SAMPLE TAKEN?
 Yes No Gas Liquid
 Character of Intermediate fluid: Clear Fresh
 Sulfur Salty Black
 Other:(describe) _____
 Sample cylinder number: _____

Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermedia Csg PSIG	Bradenhead Flow:
00:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
05:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
10:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
15:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
20:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
25:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
30:00	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		

Instantaneous Intermediate Casing PSIG at end of test: >

Comments: Post production test. 120 PSI gas flow blew down to 0 PSI within first 15 min of test no pressure or flow observed for the remainder of test. PDC will collect a sample as submit results via form 43 as soon as possible. PDC will follow up with a remediation plan via sundry.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed By: _____ Title: _____ Phone: () _____

Signed: Jenifer Hakkarinen Title: Reg TEch Date: 9/29/2020

Witnessed By: _____ Title: _____ Agency: _____