

Complaint # 200 094 236
8/3/2006



Plot Plan Soil Sample Locations

SE 1/4 of NE 1/4, SEC 10
T. 1 S. / R. 64 W.



BLANCHE KOENEKE PROPERTY

KOENEKE
SURFACE COMPOSITE
40' N, 10' W
OF PIPELINE LEAK

KOENEKE
SURFACE COMPOSITE
40' N, 10' E
OF PIPELINE LEAK

POWELL / PROPERTY LINE
POWELL
PACKARD

POWELL / PROPERTY LINE
POWELL
PACKARD

SOCO R.O.W.

SOCO R.O.W.

SOCO R.O.W.

SOCO R.O.W.

W SOCO GATHERING PIPELINE

PACKARD 1
20' N OF PIPELINE LEAK
(2' DEEP)

SE 1/4 of NE 1/4
NE 1/4 of SE 1/4

PIPELINE LEAK

PACKARD 1
20' S OF PIPELINE LEAK
(2' DEEP)

PACKARD 2
(2' ABOVE PIPELINE LEAK)

PACKARD
30' S OF PIPELINE LEAK
(SURFACE SOIL CLUMP)

BOB PACKARD PROPERTY

NE 1/4 of SE 1/4, SEC 10
T. 1 S. / R. 64 W.

KEY

X PIPELINE LEAK LOCATION
● SOIL SAMPLE LOCATION

REV	DATE	REVISION	BY	CHK'D	ENR	DATE	REV	DATE	REVISION	BY	CHK'D	ENR	DATE
0	4-25-05	DOWN FROM S.S.A. AND 30' CH	A.E.	S.A.S.									



SOCO 8-INCH GATHERING PIPELINE SPILL

ADAMS COUNTY
COLORADO

DWG. NO. \\data\Drawings\Site_Location_Map\Garden\Draw_8

Site Photographs



Photo of damage to grass caused during pipeline repair activities
Photo taken June 28, 2006

Grass raked in attempt to repair grass on July 19, 2006



Photo of tire indents and grass damage caused during pipeline repair activities.
Photo taken June 28, 2006

Tire tracks raked out and attempted repair to grass made on July 19, 2006



Photo of right-of-way and slope off the right-of-way where construction vehicles turned around and damaged grass.

Photo taken August 4, 2006



Photo of right-of-way and slope off the right-of-way where construction vehicles turned around and damaged grass.

Photo taken August 4, 2006