



1120 Lincoln Street, Suite 801, Denver Colorado 80203 (303) 894-2100 Fax (303) 894-2109

## WELL ABANDONMENT REPORT

Submit original plus one copy. This form is to be submitted as an intent whenever a plugging is planned on a borehole. The approved intent shall be valid for twelve months after the approval date after that period a new intent will be required. After the plugging is complete, this form and one copy shall again be submitted as a subsequent report of the work as actually completed.

RECEIVED

MAY 17 2010

COGCC



COGCC Operator Number: 51130

Name of Operator: Locin Oil Corporation

Address: 25231 Grogan's Mill Road, Suite 500

City: The Woodlands State: TX Zip: 77380

Contact Name & Telephone

Mark Clavenna

No: 281-362-8600 (22)

Fax: 281-419-6626

24 hour notice required,  
contact:

Tel:

API Number 05-103-08465

Well Name: Fork Unit

Well Number: 14-17-1-1

Location (QtrQtr, Sec, Twp, Rng, Meridian): SESW, Sec 14, T1S, R101W

County: Rio Blanco Federal, Indian or State Lease Number: C-02800

Field Name Douglas Creek North

Field Number 17900

### Complete the Attachment Checklist

	Oper	OGCC
Wellbore Diagram	x	
Cement Job Summary		
Wireline Job Summary		

☒ Notice of Intent to Abandon

☐ Subsequent Report of Abandonment

### Only Complete the Following Background Information for Intent to Abandon

Latitude: Longitude: GPS Data: Date of Measurement: PDOP Reading: Instrument Operator's Name:

Reason for Abandonment ☐ Dry ☐ Production Sub-economic ☐ Mechanical Problems ☐ Other

Casing to be Pulled: ☐ Yes ☒ No Top of Casing Cement: Unknown

Fish in Hole: ☐ Yes ☒ No If yes, explain details below

Wellbore has Uncemented Casing Leaks ☐ Yes ☒ No If yes, explain details below

Details:

### Current and Previously Abandoned Zones

Formation	Perforations - Top	Perforations - Bottom	Date Abandoned	Method of Isolation (None, Squeezed, BP, Cement, etc.)	Plug Depth
Mancos B	2848	2900			

### Casing History

String	Size of Hole	Size of Casing	Weight per ft	Setting Depth	Sacks Cement	Cement Bottom	Cement Top
Surface	12.25	8.625	24	189	350	180	0
Prod	7.875	5.5	15.5	3037	225	3037	

### Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 2800 with 2 sacks cmt on top. CIBP #2: Depth with sacks cmt on top

NOTE: Two (2) sacks cement required on all CIBPs.

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in ☐ Casing ☐ Open Hole ☐ Annulus  
 Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in ☐ Casing ☐ Open Hole ☐ Annulus  
 Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in ☐ Casing ☐ Open Hole ☐ Annulus  
 Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in ☐ Casing ☐ Open Hole ☐ Annulus  
 Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in ☐ Casing ☐ Open Hole ☐ Annulus

Perforate and squeeze at 1000 ft. with 50 sacks Leave at least 100 ft. in casing

Perforate and squeeze at 240 ft. with 75 sacks Leave at least 100 ft. in casing

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks Leave at least 100 ft. in casing

Set \_\_\_\_\_ sacks half in, half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.

Set \_\_\_\_\_ sacks at surface

Cut four feet below ground level, weld on plate

Dry-Hole Marker: ☒ Yes ☐ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ in. casing

\*Wireline Contractor:

Plugging date:

Type of Cement and Additives Used:

\*Cementing Contractor:

\*Attach job summaries.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name Mark Clavenna

Email: mclavenna@nclnr.com

Signed:

Title: Manager

Date: 05/11/10

OGCC Approved: Title: PE II

Date: 5/25/2010

CONDITIONS OF APPROVAL, IF ANY: