



There are no improvements within 400' except for existing Anderson #14-32 well head



K. P. Kauffman Company, Inc.

Well location map; visible improvements in 400'

Anderson-Frank #14-32 well pad

SESW section 32-T4N-R67W

Weld Co., Colorado

