

FORM  
2

Rev  
12/05

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

APPLICATION FOR PERMIT TO:

1.  Drill,  Deepen,  Re-enter,  Recomplete and Operate

2. TYPE OF WELL

- OIL  GAS  COALBED  OTHER \_\_\_\_\_  
 SINGLE ZONE  MULTIPLE ZONE  COMMINGLE ZONE

- Refiling   
Sidetrack

Document Number:

400076467

Plugging Bond Surety

20090106

3. Name of Operator: EAST CHEYENNE GAS STORAGE LLC 4. COGCC Operator Number: 10322

5. Address: 10901 WEST TOLLER DRIVE - SUITE 200  
City: LITTLETON State: CO Zip: 80127

6. Contact Name: Daniel Benedict Phone: (720)351-4014 Fax: (720)351-4200  
Email: dbenedict@mepco.us.com

7. Well Name: Jorritsma Well Number: 1

8. Unit Name (if appl): \_\_\_\_\_ Unit Number: \_\_\_\_\_

9. Proposed Total Measured Depth: 5425

WELL LOCATION INFORMATION

10. QtrQtr: SWSE Sec: 12 Twp: 11N Rng: 53W Meridian: 6  
Latitude: 40.937390 Longitude: -103.234910

Footage at Surface: 983 FNL/FSL FSL 1650 FEL/FWL FEL

11. Field Name: Lewis Creek Field Number: 49200

12. Ground Elevation: 4574 13. County: LOGAN

14. GPS Data:

Date of Measurement: 06/08/2010 PDOP Reading: 2.6 Instrument Operator's Name: Darren Veal

15. If well is  Directional  Horizontal (highly deviated) **submit deviated drilling plan.**

Footage at Top of Prod Zone: FNL/FSL \_\_\_\_\_ FEL/FWL \_\_\_\_\_ Bottom Hole: FNL/FSL \_\_\_\_\_ FEL/FWL \_\_\_\_\_

Sec: \_\_\_\_\_ Twp: \_\_\_\_\_ Rng: \_\_\_\_\_ Sec: \_\_\_\_\_ Twp: \_\_\_\_\_ Rng: \_\_\_\_\_

16. Is location in a high density area? (Rule 603b)?  Yes  No

17. Distance to the nearest building, public road, above ground utility or railroad: 983 ft

18. Distance to nearest property line: 983 ft 19. Distance to nearest well permitted/completed in the same formation: 1030 ft

20. LEASE, SPACING AND POOLING INFORMATION

Objective Formation(s)	Formation Code	Spacing Order Number(s)	Unit Acreage Assigned to Well	Unit Configuration (N/2, SE/4, etc.)
D Sandstone	DSND			
J Sandstone	JSND			

21. Mineral Ownership:  Fee  State  Federal  Indian Lease #: \_\_\_\_\_

22. Surface Ownership:  Fee  State  Federal  Indian

23. Is the Surface Owner also the Mineral Owner?  Yes  No Surface Surety ID#: \_\_\_\_\_

23a. If 23 is Yes: Is the Surface Owner(s) signature on the lease?  Yes  No

23b. If 23 is No  Surface Owners Agreement Attached or  \$25,000 Blanket Surface Bon  \$2,000 Surface Bond  \$5,000 Surface Bond

24. Using standard QtrQtr, Sec, Twp, Rng format enter entire mineral lease description upon which this proposed wellsite is located (attach separate sheet/map if you prefer):

25. Distance to Nearest Mineral Lease Line: 983 ft 26. Total Acres in Lease: 640

**DRILLING PLANS AND PROCEDURES**

27. Is H2S anticipated?  Yes  No If Yes, attach contingency plan.

28. Will salt sections be encountered during drilling?  Yes  No

29. Will salt (>15,000 ppm TDS CL) or oil based muds be used during drilling?  Yes  No

30. If questions 27 or 28 are yes, is this location in a sensitive area (Rule 903)?  Yes  No **If 28, 29, or 30 are "Yes" a pit permit may be required.**

31. Mud disposal:  Offsite  Onsite

Method:  Land Farming  Land Spreading  Disposal Facility Other: \_\_\_\_\_

Note: The use of an earthen pit for Recompletion fluids requires a pit permit (Rule 905b). If air/gas drilling, notify local fire officials.

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bottom	Cement Top
SURF	13+5/8	9+5/8	25.4	214	160	214	0
1ST	8+5/8	5+1/2	15.5	5,423	250	5,423	4,210

32. BOP Equipment Type:  Annular Preventer  Double Ram  Rotating Head  None

33. Comments The well is within the gas storage area. The well is plugged and abandoned. We wish to recomplete this well to the D Sandstone and utilize it as an Injection/Withdrawal well in the gas storage project.

34. Location ID: \_\_\_\_\_

35. Is this application in a Comprehensive Drilling Plan ?  Yes  No

36. Is this application part of submitted Oil and Gas Location Assessment ?  Yes  No

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Daniel Benedict

Title: engineer Date: 7/14/2010 Email: dbenedict@mepco.us.com

Based on the information provided herein, this Application for Permit-to-Drill complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: *David S. Neslin* Director of COGCC Date: 8/17/2010

**API NUMBER**  
05 075 07130 00

Permit Number: \_\_\_\_\_ Expiration Date: 8/16/2012

**CONDITIONS OF APPROVAL, IF ANY:** \_\_\_\_\_

All representations, stipulations and conditions of approval stated in the Form 2A for this location shall constitute representations, stipulations and conditions of approval for this Form 2 Permit-to-Drill and are enforceable to the same extent as all other representations, stipulations and conditions of approval stated in this Permit-to-Drill.

- 1) Provide 24 hour notice of MIRU to Colby Horton at 970-467-2517 or e-mail at colby.horton@state.co.us.
- 2) Place stage cement to comply with Rule 317.i, set stage cement from 1300' to at least 50' above the existing surface casing shoe, and confirm cement coverage from TD to a minimum of 200' above D Sand. Verify coverage with cement bond log.
- 3) Pressure test the casing to confirm integrity.
- 4) Within 30 days after recomplete, submit Form 5 with CBL to document remedial cement in accordance with Rule 308A (change of wellbore configuration) and Form 5A to document new status of both formations in accordance with Rule 308B.

### Attachment Check List

Att Doc Num	Name	Doc Description
1726061	SURFACE CASING CHECK	LF@2524212 1726061
400076467	FORM 2 SUBMITTED	LF@2507316 400076467
400076486	PLAT	LF@2507317 400076486
400076488	LOCATION PICTURES	LF@2507318 400076488
400076490	TOPO MAP	LF@2507319 400076490
400076491	LOCATION PHOTO	LF@2507320 400076491

Total Attach: 6 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	well is currently P&A, changed from recomplete to re-enter, OK per Daniel Benedict	8/17/2010 10:27:04 AM

Total: 1 comment(s)

Error: Subreport could not be shown.