

400' Offset
From Pad
Disturbance
Limits

SW $\frac{1}{4}$ SE $\frac{1}{4}$
SE $\frac{1}{4}$ SE $\frac{1}{4}$

RBC 83

Two-Track Road

Section 34
T. 1 S. R. 98 W.,
6th P.M.

N14°W 203'
to County Road
CL Pad
Reference Point

Two-Track Road

S2°05'34"W
200.41'
to Fence
Corner

Proposed Pad

Section 3
T. 2 S. R. 98 W.,
6th P.M.


Found 1982 BLM
Aluminum Cap
E $\frac{1}{16}$ S34 & S3

Fenceline

Fenceline



Reference Point
Center of Pad Stake
Latitude (NAD 83)
N39.913147°
Longitude (NAD 83)
W108.373974°



SURVEYORS STATEMENT:

I, ELWOOD BARRY GILES, BEING A REGISTERED LAND SURVEYOR IN THE STATE OF COLORADO, DO HERBY CERTIFY THAT THIS PLAT REPRESENTS A SURVEY PERFORMED BY ME, OR UNDER MY DIRECT SUPERVISION JUNE 3, 2010 AND THE REFERENCE POINT HAS BEEN STAKED AS SHOWN HEREON.

Elwood Barry Giles
ELWOOD BARRY GILES
COLORADO LS 38150

25 AUG, 2010

DATE



SGM INC.
118 W. 6th Street, Suite 200
Glenwood Springs, Colorado 81601
(970) 945-1004 (FAX 945-5948)
Meeker, Colorado (970) 878-5180

Scale: 1"=1000'

Sheet 1A of 11

RG Fed 2G-34D

Addendum to Well Location Plat - RG Federal 2G-34D

SE 1/4 Sect. 34, T. 1 S., R. 98W., 6th P.M., Rio Blanco County, CO

Job# 2008-111.008

Date: 8.24.2010

By: reb

File: PLC Ryan.dwg