


KINDER MORGAN CO2 COMPANY, L.P.  
Goodman Point - II  
2431' FSL & 160' FWL surface location  
6796' grd el from GPS  
Section I, T.36 N, R.18 W, NMPM  
2422' FSL & 2160' FWL bottom hole  
Section I T.36 N R.18 W NMPM  
Montezuma County CO

Date of survey 09/18/07  
Date of plat 09/20/07



The above is true and correct to my knowledge and belief

ANDERSON ENGINEERING COMPANY INC - 977 WEST 2100 SOUTH SALT LAKE CITY UT 84119