



# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109



FOR OGCC USE ONLY

## ACCIDENT REPORT

As required by Rule 602.b.

Report taken by:

### DESCRIPTION OF ACCIDENT (Please be as specific as possible)

<b>Name of Operator:</b> <u>XOG OPERATING, LLC</u>	<b>Location</b>
<b>Date of Incident:</b> <u>2/15/11</u>	<b>County:</b> <u>MOFFAT</u>
<b>Type of Facility (well, tank battery, flow line, pit):</b> <u>TANK BATTERY</u>	<b>Field Name:</b> <u>PEACHTREE</u>
<b>Well Name and Number:</b> <u>SUGARLOAF 34-1</u>	<b>QtrQtr:</b> <u>SWSW</u> <b>Section:</b> <u>34</u>
<b>API Number:</b> <u>05-081-06606</u>	<b>Township:</b> <u>12N</u> <b>Range:</b> <u>101W</u>
<b>Connect to Accident (land owner, royalty owner, etc.):</b> <u>OPERATOR</u>	<b>Meridian:</b> _____

Provide a detailed description of the accident, problem, and cause (equipment failure, human error, etc.):

2/15/11, Approximately 7:00 am MST Questar called Robin Folks, our pumper, and notified him of a fire. Robin called the Sheriff's department and asked them to dispatch the fire department.

2/15/11, approximately 7:20 am MST Nick Hood at our office received a call from our pumper, Robin Folks, on location stating that the tank at the battery was on fire. Upon arrival Robin had immediately shut in the well. The fire burned itself out. The BLM had the representative below on location. No injuries. XOG will repair damages and return well to production. Cause of fire unknown. Suspect malfunction on separator. Lost approximately 100 bbls condensate due to tank fire.

### OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact Person	Response
2/15/11	Bureau of Land management	Roy Wallis	On Location
2/15/11	Moffat Co., Sheriff Dept.		Called XOG Midland Office

Accident Tracking No: \_\_\_\_\_