



TREATMENT NUMBER
F0201010
STAGE 2

DATE 4/20/11
JOB TYPE Repair
CEMENT RUN# 2304

WELL NAME AND NO. Building 23-30 T1 LOCATION (LEGAL) SW/4E-30-T128-445W RIG NAME Pioneer Rig # 2916 Im. Top

COUNTY Brown Basin PERMITATION Brown/Venoco APT NO. 02-071-0706 ARRIVE ON LOCATION TIME: 8:45 DATE: 4/20/11 RIG UP TIME: 9:00 DATE: 4/20/11 CEMENT SUPERVISOR: Frank L. Gonzalez LEFT LOCATION TIME: 14:30 DATE: 4/20/11

TIME	THRO	LBS ANTIMAS PRESTRIK CSO	VOLUME PUMPED INC	CUM	JOB SCHEDULED FOR DATE	FLUID TYPE	DENSITY	COMMENT
9:30								Balby Mending Piston pump
9:35								Piston Test
9:54	1000		1	1		H2O	8.3	Pressure Up and Hold for 15 minutes
9:55	400		5	2.5		H2O	8.3	Pressure Up and Hold for 15 minutes
9:58	400					H2O	8.3	Pressure Up and Hold for 15 minutes
10:00	400					H2O	8.3	Pressure Up and Hold for 15 minutes
10:12	400					H2O	8.3	Pressure Up and Hold for 15 minutes
10:29	100		3	7.5		CMT>	15	Batch remainder of Cement and Pump to Blowback Tank
10:34	100		40	47.5		H2O	8.3	Wash Up Pumps and lines
11:15								Rig Down

JOB SUMMARY:
Lost to BOP - Can not pump into it

ADDITIONAL NOTES: